



**TITLE** : Report on the evaluation of the fire propagation properties of the **IsoBoard** Extruded Polystyrene insulation system product range using the **SANS 10177 – Part 5, 10 and 11 (H & V)** test protocol in terms of **SANS 428**

**REQUESTED BY** : Isofoam South Africa (Pty) Ltd.  
PO Box 1002  
**Cape Gate**  
7562

**CONTRACT No** : FTC15/029

**AUTHOR(S)** : J.S. Strydom, P.J. Strydom

**DATE** : 24 August 2015

Copyright is vested with **FIRELAB cc**

The use of this report is subject to the condition that it will only be published in full or an abridged version approved by **FIRELAB**

## TABLE OF CONTENTS

LIST OF FIGURES AND TABLES.....	2
1. INTRODUCTION.....	4
2. SAMPLE DESCRIPTION .....	4
3. TEST PROCEDURES.....	5
3.1. <b>SANS 10177 – PART 5: 2012 (COMBUSTIBILITY)</b> .....	5
3.2. <b>SANS 10177 – PART 10 (FLAME SPREAD)</b> .....	6
3.3. <b>SANS 10177 – PART 11, HORIZONTAL (CLASSIFICATION)</b> .....	7
3.4. <b>SANS 10177 – PART 11, VERTICAL (CLASSIFICATION)</b> .....	9
4. TEST RESULTS .....	11
4.1. <b>SANS 10177 – PART 5: 2012 (COMBUSTIBILITY)</b> .....	11
4.2. <b>SANS 10177 – PART 10 (FLAME SPREAD)</b> .....	12
4.2.1. 25 MM ISOBOARD PANEL.....	12
4.2.2. 30 MM ISOBOARD PANEL.....	18
4.2.3. 40 MM ISOBOARD PANEL.....	23
4.2.4. 50 MM ISOBOARD PANEL.....	29
4.2.5. 80 MM ISOBOARD PANEL.....	35
4.3. <b>SANS 10177 – PART 11, HORIZONTAL (CLASSIFICATION)</b> .....	41
4.4. <b>SANS 10177 – PART 11, VERTICAL (CLASSIFICATION)</b> .....	49
5. DISCUSSION OF RESULTS.....	54
6. CONCLUSIONS.....	55
ANNEXURE "A" .....	56

## LIST OF FIGURES AND TABLES

Figure 3.1.1: Electrically Heated Furnace used in the <b>SANS 10177 – Part 5</b> test .....	5
Figure 3.2.1: Diagram of <b>SANS 10177 – 10</b> inverted channel testing facility .....	6
Figure 3.3.1: <b>SANS 10177 – Part 11</b> test facility with specimen frames .....	8
Figure 3.3.2: Typical roof test installation in the <b>SANS 10177 – Part 11</b> facility .....	8
Figure 3.4.1: <b>SANS 10177-11</b> facility plan view for vertical test .....	10
Figure 3.4.2: Typical side-cladding installation in <b>SANS 10177-11</b> facility .....	10
Table 4.1.1: Combustibility results from the <b>SANS 10177-5</b> test .....	11
Table 4.2.1.1: Observations made during the <b>SANS 10177 – Part 10</b> test .....	12
Figure 4.2.1.1: The test installation prior to ignition of the Fire Source .....	13
Figure 4.2.1.2: Joint opening up above Fire Source .....	13
Figure 4.2.1.3: Material softening and starting to drape and drop out above the Fire Source .....	14
Figure 4.2.1.4: Heat damage and material draping up to 2 meters .....	14
Figure 4.2.1.5: Material dropping out to 2 meter mark and draping up to 4 meters .....	15
Figure 4.2.1.6: Heat damage up to 6 meter mark and dropping out up to 4 meters .....	15
Figure 4.2.1.7: Full length heat damage with material dropping out to 4 meters .....	16
Figure 4.2.1.8: Test specimen at conclusion of <b>SANS 10177 – 10</b> test .....	16
Figure 4.2.1.9: Temperatures recorded during the <b>SANS 10177 – Part 10</b> test .....	17
Table 4.2.2.1: Observations made during the <b>SANS 10177 – Part 10</b> test .....	18
Figure 4.2.1.1: The test installation prior to ignition of the Fire Source .....	19
Figure 4.2.1.2: Heat damage above Fire Source with joint opening .....	19
Figure 4.2.1.3: Material draping up to 2 meters .....	20
Figure 4.2.1.4: Material dropping out and draping up to 4 meters .....	20
Figure 4.2.1.5: Full length heat damage with material draping out up to 6 meters .....	21
Figure 4.2.1.6: Test specimen at conclusion of <b>SANS 10177 – 10</b> test .....	21
Figure 4.2.2.7: Temperatures recorded during the <b>SANS 10177 – Part 10</b> test .....	22
Table 4.2.3.1: Observations made during the <b>SANS 10177 – Part 10</b> test .....	23
Figure 4.2.3.1: The test installation prior to ignition of the Fire Source .....	24
Figure 4.2.3.2: Material shrinking and joint starting to open up .....	24
Figure 4.2.3.3: Material discolouring with joint opening above Fire Source .....	25
Figure 4.2.3.4: Material softening and flowing down in Ignition Source Area .....	25
Figure 4.2.3.5: Material draping and dropping out up to 2 meter mark .....	26
Figure 4.2.3.6: Material draping up to 4 meter mark .....	26
Figure 4.2.3.7: Heat damage up to 6 meter mark with material dropping out .....	27
Figure 4.2.3.8: Test specimen at conclusion of <b>SANS 10177 – 10</b> test .....	27
Figure 4.2.3.9: Temperatures recorded during the <b>SANS 10177 – Part 10</b> test .....	28
Table 4.2.4.1: Observations made during the <b>SANS 10177 – Part 10</b> test .....	29
Figure 4.2.4.1: The test installation prior to ignition of the Fire Source .....	30
Figure 4.2.4.2: Shrinking of material visible and joint separating above Fire Source .....	30
Figure 4.2.4.3: Molten material dropping out within Fire Source Area .....	31
Figure 4.2.4.4: Softened material dropping out up to 2 meter mark .....	31

Figure 4.2.4.5: Material draping and dropping out up to 4 meter mark .....	32
Figure 4.2.4.6: Heat damage on joint full length (0 to 7 meters) .....	32
Figure 4.2.4.7: Material draping and dropping out up to 5 meter mark .....	33
Figure 4.2.4.8: Test specimen at conclusion of <b>SANS 10177 – 10</b> test .....	33
Figure 4.2.4.9: Temperatures recorded during the <b>SANS 10177 – Part 10</b> test .....	34
Table 4.2.5.1: Observations made during the <b>SANS 10177 – Part 10</b> test.....	35
Figure 4.2.5.1: The test installation prior to ignition of the Fire Source .....	36
Figure 4.2.5.2: Material surface changing with joint separating above Fire Source .....	36
Figure 4.2.5.3: Molten material at joint starts to drape .....	37
Figure 4.2.5.4: Molten material flowing out above Fire Source – Joint separated up to 2 meter mark.....	37
Figure 4.2.5.5: Material draping and dropping out up to 2 meter mark .....	38
Figure 4.2.5.6: Separation of joint reaches full length (0 to 7 meters).....	38
Figure 4.2.5.7: All material up to 2 meter mark dropped out .....	39
Figure 4.2.5.8: Test specimen at conclusion of <b>SANS 10177 – 10</b> test .....	39
Figure 4.2.5.9: Temperatures recorded during the <b>SANS 10177 – Part 10</b> test .....	40
Table 4.3.1: Observations recorded during the <b>SANS 10177-11</b> test.....	41
Figure 4.3.1: The <b>SANS 10177-11</b> test installation prior to ignition of the Fire Source .....	42
Figure 4.3.2: Edges of joints above Fire Source becomes rounded due to shrinkage .....	42
Figure 4.3.3: Surface coagulation visible and joints separating due to shrinkage .....	43
Figure 4.3.4: Molten material above Fire Source starts to flow .....	43
Figure 4.3.5: Material above Fire Source draping and dropping out .....	44
Figure 4.3.6: Boards in 2 <sup>nd</sup> bay (2 to 4 meters) starts to drape .....	44
Figure 4.3.7: Fire Source (Crib) starting to collapse – Boards draping up to 3 meter mark.....	45
Figure 4.3.8: Fire Source (Crib) completely collapsed – Boards draping up to 4 meter mark .....	45
Figure 4.3.9: Material draping close to sprinkler head and over sprinkler pipes in rear .....	46
Figure 4.3.10: Test installation at conclusion of <b>SANS 10177 – Part 11 (Horizontal)</b> test.....	46
Figure 4.3.11: Temperatures recorded on the front sample frame during the <b>SANS 10177-11</b> test .....	47
Figure 4.3.12: Temperatures recorded on the rear sample frame during the <b>SANS 10177-11</b> test.....	48
Table 4.4.1: Observations recorded during the <b>SANS 10177-11</b> test.....	49
Figure 4.4.1: Test installation prior to ignition of the two Fire Source cribs .....	50
Figure 4.4.2: Material melting and bubble forming behind Crib.....	50
Figure 4.4.3: Coagulation of material behind Cribs .....	51
Figure 4.4.4: Coagulation of material exposing sheeting .....	51
Figure 4.4.5: Molten material starting to flow down .....	52
Figure 4.4.6: Heat damage visible on horizontally installed material.....	52
Figure 4.4.7: Cribs starting to collapse – No ignition occurred.....	53
Figure 4.4.8: Test installation after the <b>SANS 10177-11 (V)</b> test was concluded.....	53

## 1. INTRODUCTION

The purpose of the investigation was to evaluate the fire propagation properties of the **IsoBoard** Extruded Polystyrene product range for industrial and commercial buildings in terms of **SANS 428** as supplied by **Isofoam South Africa (Pty) Ltd**.

## 2. SAMPLE DESCRIPTION

The **IsoBoard** products had the following characteristics:

### Physical Properties:

<i>Mass:</i>	32 – 36	kg/m <sup>3</sup>
<i>Thickness:</i>	25 – 80	mm
<i>Width:</i>	600	mm
<i>Length:</i>	6 000	mm
<i>Batch Number:</i>		Unknown
<i>Manufacturing Date:</i>		Unknown

### Product Composition:

<i>Material:</i>	32 – 36	kg/m <sup>3</sup> Extruded Polystyrene (XPS)
<i>Facings:</i>	–	None

### Joint details:

<i>Joint (25 – 50 mm):</i>	Tongue and Groove (T & G)
<i>Joint (60 – 80 mm):</i>	Shiplap

### Intended usage:

*Over-purlin under-roof insulation in industrial and commercial buildings using profiled metal roof sheeting.*

### Generic Identification:

*White high density Extruded Polystyrene (XPS)*

Product information as supplied by **Isofoam South Africa (Pty) Ltd** can be found in **Annexure "A"**.

### 3. TEST PROCEDURES

#### 3.1. SANS 10177 – PART 5: 2012 (COMBUSTIBILITY)

For this evaluation, a number of 40 x 40 mm samples was prepared and in turn placed on a sample holder and lowered into the standard **SANS 10177-5** electrically-heated furnace, which has been pre-set to have a furnace enclosure temperature of 750 °C. The standard test duration is 10 minutes.

The test criteria for non-combustibility are that the specimen should neither increase the furnace enclosure temperature by more than 50 °C nor support flaming continuously for more than 10 seconds during the exposure period. Should either of these criteria not be met, the material will be regarded as combustible at 750 °C.




Figure 3.1.1: Electrically Heated Furnace used in the **SANS 10177 – Part 5** test

### 3.2. SANS 10177 – PART 10 (FLAME SPREAD)

The installation was representative as would normally be done in practice for an over-purlin under-roof installation in buildings using profiled roof sheeting. The specimens were installed according to manufacturer’s installation instructions in the channel tunnel facility shown in Figure 3.2.1.

The fire-spread properties of the insulation material tested, envisaged for use in buildings, are classified according to **Annex C** of **SANS 428**, Surface fire properties, also taking in consideration the limitations regarding the use of non-combustible materials described in **SANS 10400 – T**.

Temperatures were measured during the investigation with thermocouples located 20 mm below the installation at 1 m centres. The test installation was exposed to the thermal output of three litres of n-hexane, which was placed in the fire source tray. Temperatures were continuously recorded and observations were noted of the behaviour of the material.




Figure 3.2.1: Diagram of **SANS 10177 – 10** inverted channel testing facility

### **3.3. SANS 10177 – PART 11, HORIZONTAL (CLASSIFICATION)**

The large-scale fire propagation properties of the system were evaluated by performing a test in the **FIRELAB** large-scale roof insulation test facility. A schematic diagram of the test facility with the specimen frames are shown in Figure 3.3.1 and 3.3.2.

The ignition source for the under-roof evaluation was constructed from 60 kg dry 38 mm x 38 mm SA Pine sticks stacked in an open-crib configuration to form a 1 000 mm x 750 mm x 480 mm high crib. The pack was ignited with commercial firelighters at each corner, in order to simulate a fire with slow heat build-up. The maximum heat output of the fire source (approximately 2.5 MW based on previous research) occurred after approximately 12 minutes.

The fire source was located at one end of the facility, approximately 1.5 m from the front end, 1.5 m from the side and 1.5 m from the center line of the specimen frame. The position of the crib is indicated on Figure 3.3.1. No mass loss measurements were taken during the evaluations.

This test was performed simulating a roof insulation system. This evaluation investigated the fire propagation properties of the Extruded Polystyrene insulation with the purlins positioned across the width of the test facility. A schematic side view of a typical roof test installation is shown in Figure 3.3.2.

For this evaluation the specimen frames were aligned in such a way that the roof slope was equal to 3 degrees. The distance between the top of the fire source and the roof directly above it was 2.7 metres.






Figure 3.3.1: SANS 10177 – Part 11 test facility with specimen frames




Figure 3.3.2: Typical roof test installation in the SANS 10177 – Part 11 facility

### **3.4. SANS 10177 – PART 11, VERTICAL (CLASSIFICATION)**

The fire propagation properties associated with the use of this insulation system in a side cladding application were investigated in terms of the relevant section of **SANS 10177-11**.

A vertical specimen frame was fitted to the front end of the test installation against the first horizontal hanging frame. The insulation material was installed onto the inside between the horizontal purlins. The fire source was placed 600 mm either side of the center of the vertical frame. A typical installation is shown schematically in Figure 3.4.1 and Figure 3.4.2.

The fire source consisted of two packs of 7.5 kg consisting of 38 mm x 38 mm pine sticks, each 300 mm in length, four per layer and ten layers high.

No temperatures were recorded during this evaluation. The criterion that will be applied when assessing whether the material is suitable for vertical applications is that flame spread onto the roof portion will not be allowed.




Figure 3.4.1: **SANS 10177-11** facility plan view for vertical test




Figure 3.4.2: Typical side-cladding installation in **SANS 10177-11** facility

## 4. TEST RESULTS

### 4.1. SANS 10177 – PART 5: 2012 (COMBUSTIBILITY)

Should the furnace enclosure temperature be raised above 800 °C or the material support flaming for longer than 10 seconds during the exposure period, the material will be regarded as combustible at 750 °C.

Table 4.1.1 below gives the individual burn times and heat contribution for the 6 specimens tested within the **SANS 10177 – Part 5** facility.

Isofoam South Africa (Pty) Ltd – IsoBoard (32 – 36 kg/m <sup>3</sup> )				
Sample number	Time to ignition (mm:ss)	Time to extinguishment (mm:ss)	Burn time (mm:ss)	Heat Contribution (°C)
1	00:03	00:30	00:27	< 50
2	00:02	00:32	00:30	< 50
3	00:06	00:34	00:28	< 50
4	00:06	00:34	00:28	< 50
5	00:07	00:39	00:32	< 50
<b>Classification:</b>			<b>Combustible</b>	

Table 4.1.1: Combustibility results from the **SANS 10177-5** test

The material would therefore be regarded as combustible at 750 °C given that the burn times did exceed 10 seconds. The furnace enclosure temperature was not however increased by more than 50 °C.

## 4.2. SANS 10177 – PART 10 (FLAME SPREAD)

### 4.2.1. 25 MM ISOBOARD PANEL

The test installation in the **SANS 10177 – Part 10** facility prior to ignition of the fire source is shown in Figure 4.2.1.1 and at the conclusion of the test in Figure 4.2.1.8.

Observations made during **SANS 10177-10** test are depicted in Table 4.2.1.1 below:

Isofoam South Africa (Pty) Ltd – 25 mm IsoBoard	
OBSERVATIONS DURING THE <b>SANS 10177 – PART 10</b> TEST	
TIME	OBSERVATION
00:00	– Test Started –
00:35	Joint started opening
01:10	Material shrinking away
01:25	Joint open
01:50	Softened material draping and dropping down
05:40	Material drape up to 2 meters
06:00	Heat damage up to 3 meters
08:50	Material drape up to 4 meters and starting to drop down
09:20	Heat damage past 4 meters
10:40	Molten droplets up to 2 meters (trapped material)
12:00	Material draped up to 6 meters
13:15	Fire Source consumed – Test end –
<u>Note(s):</u>	Molten debris above Fire Source No ignition during test

Table 4.2.1.1: Observations made during the **SANS 10177 – Part 10** test

The temperatures recorded during the test in the **SANS 10177-10** facility are depicted graphically in Figure 4.2.1.9.



Figure 4.2.1.1: The test installation prior to ignition of the Fire Source




Figure 4.2.1.2: Joint opening up above Fire Source



Figure 4.2.1.3: Material softening and starting to drape and drop out above the Fire Source



Figure 4.2.1.4: Heat damage and material draping up to 2 meters



Figure 4.2.1.5: Material dropping out to 2 meter mark and draping up to 4 meters



Figure 4.2.1.6: Heat damage up to 6 meter mark and dropping out up to 4 meters





Figure 4.2.1.7: Full length heat damage with material dropping out to 4 meters



Figure 4.2.1.8: Test specimen at conclusion of **SANS 10177 - 10** test




Figure 4.2.1.9: Temperatures recorded during the **SANS 10177 – Part 10** test

#### 4.2.2. 30 MM ISOBOARD PANEL

The test installation in the **SANS 10177 – Part 10** facility prior to ignition of the fire source is shown in Figure 4.2.2.1 and at the conclusion of the test in Figure 4.2.2.6.

Observations made during **SANS 10177-10** test are depicted in Table 4.2.2.1 below:

Isofoam South Africa (Pty) Ltd – 30 mm IsoBoard	
OBSERVATIONS DURING THE <b>SANS 10177 – PART 10</b> TEST	
TIME	OBSERVATION
00:00	– Test Started –
00:50	Material started shrinking and joint open
02:00	Joint completely open above Fire Source
02:25	Material starts draping and dropping out
04:00	Heat damage and material dropping out up to 2 meters
06:15	Material draping past 2 meter mark
09:35	Material dropping out up to 4 meters and draping up to 6 meters
14:17	Fire Source consumed – <b>Test end</b> –
<u>Note(s):</u>	Molten debris above Fire Source No ignition during test

Table 4.2.2.1: Observations made during the **SANS 10177 – Part 10** test

The temperatures recorded during the test in the **SANS 10177-10** facility are depicted graphically in Figure 4.2.2.7.



Figure 4.2.1.1: The test installation prior to ignition of the Fire Source



Figure 4.2.1.2: Heat damage above Fire Source with joint opening



Figure 4.2.1.3: Material draping up to 2 meters



Figure 4.2.1.4: Material dropping out and draping up to 4 meters



Figure 4.2.1.5: Full length heat damage with material draping out up to 6 meters



Figure 4.2.1.6: Test specimen at conclusion of **SANS 10177 - 10** test




Figure 4.2.2.7: Temperatures recorded during the **SANS 10177 – Part 10** test

### 4.2.3. 40 MM ISOBOARD PANEL

The test installation in the **SANS 10177 – Part 10** facility prior to ignition of the fire source is shown in Figure 4.2.3.1 and at the conclusion of the test in Figure 4.2.3.8.

Observations made during **SANS 10177-10** test are depicted in Table 4.2.3.1 below:

Isofoam South Africa (Pty) Ltd – 40 mm IsoBoard	
OBSERVATIONS DURING THE <b>SANS 10177 – PART 10</b> TEST	
TIME	OBSERVATION
00:00	– Test Started –
01:00	Material starts shrinking above Fire Source
01:20	Joint starts to pull open
01:50	Discoloration of material started above Fire Source
02:10	Joint completely open
03:00	Material softening and flowing down
04:15	Molten material draping down
08:00	Material continue to flow down
09:00	Material draping over purlin at 2 meter mark
09:40	Softening of material continue past 2 meter mark and draping down
09:45	Material trapped on purlin in Ignition Source Area starts burning
13:00	Fire Source starting to decay
14:00	Fire Source consumed – Test end –
<u>Note(s):</u>	–

Table 4.2.3.1: Observations made during the **SANS 10177 – Part 10** test

The temperatures recorded during the test in the **SANS 10177-10** facility are depicted graphically in Figure 4.2.3.9.





Figure 4.2.3.1: The test installation prior to ignition of the Fire Source




Figure 4.2.3.2: Material shrinking and joint starting to open up



Figure 4.2.3.3: Material discolouring with joint opening above Fire Source



Figure 4.2.3.4: Material softening and flowing down in Ignition Source Area



Figure 4.2.3.5: Material draping and dropping up to 2 meter mark



Figure 4.2.3.6: Material draping up to 4 meter mark



Figure 4.2.3.7: Heat damage up to 6 meter mark with material dropping out



Figure 4.2.3.8: Test specimen at conclusion of **SANS 10177 – 10** test




Figure 4.2.3.9: Temperatures recorded during the **SANS 10177 – Part 10** test

#### 4.2.4. 50 MM ISOBOARD PANEL

The test installation in the **SANS 10177 – Part 10** facility prior to ignition of the fire source is shown in Figure 4.2.4.1 and at the conclusion of the test in Figure 4.2.4.8.

Observations made during **SANS 10177-10** test are depicted in Table 4.2.4.1 below:

Isofoam South Africa (Pty) Ltd – 50 mm IsoBoard	
OBSERVATIONS DURING THE <b>SANS 10177 – PART 10</b> TEST	
TIME	OBSERVATION
00:00	– Test Started –
00:35	Material softening and shrinking away at joint
00:55	Material started shrinking on joint above Fire Source
01:15	Softening and shrinking of material surface above Fire Source
01:50	Joint opens up completely
02:57	Molten droplets within the Fire Source Area
03:50	Softened debris dropping out – Joint separate up to 1 meter mark
08:35	Draping material drops out to 2 meter mark
10:55	Draping material drops out to 3 meter mark
12:35	Draping material drops out to 4 meter mark
13:10	Fire Source starting to decay
14:00	Fire Source consumed – <b>Test end</b> –
<u>Note(s):</u>	Molten droplets within Fire Source Area (0 to 2 meters) Heat damage on joint full length (0 to 7 meters)

Table 4.2.4.1: Observations made during the **SANS 10177 – Part 10** test

The temperatures recorded during the test in the **SANS 10177-10** facility are depicted graphically in Figure 4.2.4.9.



Figure 4.2.4.1: The test installation prior to ignition of the Fire Source




Figure 4.2.4.2: Shrinking of material visible and joint separating above Fire Source



Figure 4.2.4.3: Molten material dropping out within Fire Source Area



Figure 4.2.4.4: Softened material dropping out up to 2 meter mark





Figure 4.2.4.5: Material draping and dropping out up to 4 meter mark



Figure 4.2.4.6: Heat damage on joint full length (0 to 7 meters)



Figure 4.2.4.7: Material draping and dropping out up to 5 meter mark



Figure 4.2.4.8: Test specimen at conclusion of **SANS 10177 - 10** test




Figure 4.2.4.9: Temperatures recorded during the **SANS 10177 – Part 10** test

#### 4.2.5. 80 MM ISOBOARD PANEL

The test installation in the **SANS 10177 – Part 10** facility prior to ignition of the fire source is shown in Figure 4.2.5.1 and at the conclusion of the test in Figure 4.2.5.8.

Observations made during **SANS 10177-10** test are depicted in Table 4.2.5.1 below:

Isofoam South Africa (Pty) Ltd – 80 mm IsoBoard	
OBSERVATIONS DURING THE <b>SANS 10177 – PART 10</b> TEST	
TIME	OBSERVATION
00:00	– Test Started –
00:45	Joint start to shrink away
01:00	Material surface texture start to change above Fire Source
04:05	Charring/darkening of material surface above Fire Source
04:30	Material starts draping along the joint
05:40	Material starts dropping out up to 2 meter mark
11:00	Joint fully separated over entire length (0 to 7 meters)
14:00	Fire Source consumed – <b>Test end</b> –
<u>Note(s):</u>	–

Table 4.2.5.1: Observations made during the **SANS 10177 – Part 10** test

The temperatures recorded during the test in the **SANS 10177-10** facility are depicted graphically in Figure 4.2.5.9.



Figure 4.2.5.1: The test installation prior to ignition of the Fire Source



Figure 4.2.5.2: Material surface changing with joint separating above Fire Source



Figure 4.2.5.3: Molten material at joint starts to drape



Figure 4.2.5.4: Molten material flowing out above Fire Source – Joint separated up to 2 meter mark



Figure 4.2.5.5: Material draping and dropping out up to 2 meter mark




Figure 4.2.5.6: Separation of joint reaches full length (0 to 7 meters)



Figure 4.2.5.7: All material up to 2 meter mark dropped out



Figure 4.2.5.8: Test specimen at conclusion of **SANS 10177 – 10** test






Figure 4.2.5.9: Temperatures recorded during the **SANS 10177 – Part 10** test

### 4.3. SANS 10177 – PART 11, HORIZONTAL (CLASSIFICATION)

Observations made during the **SANS 10177-11** test are depicted in Table 4.3.1 below:

Isofoam South Africa (Pty) Ltd – 80 mm IsoBoard	
OBSERVATIONS MADE DURING THE <b>SANS 10177 – PART 11</b> TEST	
TIME	OBSERVATION
00:00	– Test Started –
03:35	Shrinkage occurs rounding edges of joint
04:55	Surface coagulation started on material above Fire Source
05:50	Joints start shrinking in 2 <sup>nd</sup> bay (2 to 4 meters)
07:05	Discoloration/Charring of joint above Fire Source
08:00	Joint completely separates above the Fire Source
08:45	Sample starts softening and flowing above Fire Source
09:15	Molten debris starts dropping out
12:05	Boards in 2 <sup>nd</sup> bay (2 to 4 meters) starting to drape
13:25	Fire Source (Crib) starting to collapse
14:40	Joints up to 4 <sup>th</sup> bay (0 to 8 meters) starts to shrink
26:00	Fire Source (Crib) consumed – End of Test –
<u>Note(s):</u>	No ignition occurred during the test

Table 4.3.1: Observations recorded during the **SANS 10177-11** test

The test installation in the **SANS 10177-11** facility prior to ignition of the Fire Source (Crib) and after the test was concluded is shown in Figure 4.3.1 and 4.3.10 respectively. The temperatures recorded by the thermocouples (TC) during the test are depicted graphically in Figures 4.3.11 and 4.3.12.



Figure 4.3.1: The **SANS 10177-11** test installation prior to ignition of the Fire Source



Figure 4.3.2: Edges of joints above Fire Source becomes rounded due to shrinkage



Figure 4.3.3: Surface coagulation visible and joints separating due to shrinkage



Figure 4.3.4: Molten material above Fire Source starts to flow



Figure 4.3.5: Material above Fire Source draping and dropping out



Figure 4.3.6: Boards in 2<sup>nd</sup> bay (2 to 4 meters) starts to drape



Figure 4.3.7: Fire Source (Crib) starting to collapse – Boards draping up to 3 meter mark



Figure 4.3.8: Fire Source (Crib) completely collapsed – Boards draping up to 4 meter mark



Figure 4.3.9: Material draping close to sprinkler head and over sprinkler pipes in rear



Figure 4.3.10: Test installation at conclusion of **SANS 10177 – Part 11 (Horizontal)** test




Figure 4.3.11: Temperatures recorded on the front sample frame during the **SANS 10177-11** test






Figure 4.3.12: Temperatures recorded on the rear sample frame during the **SANS 10177-11** test

#### 4.4. SANS 10177 – PART 11, VERTICAL (CLASSIFICATION)

Observations made during the **SANS 10177-11** test are depicted in Table 4.4.1 below:

Isofoam South Africa (Pty) Ltd – 80 mm IsoBoard	
OBSERVATIONS MADE DURING THE SANS 10177 – PART 11 (VERTICAL) TEST	
TIME	OBSERVATION
00:00	– Test Started –
01:50	Bubbles forming on surface and shrinking started
03:30	Discoloration of panel surface started
05:15	Coagulation of material exposing cladding
06:10	Molten material start to flow down
06:50	Heat exposure visible on horizontal roof cladding
09:30	Horizontal roof cladding above left crib starting to deform
12:00	Left crib starting to collapse
13:50	Right crib starting to collapse
15:15	Right crib collapses
18:25	Left crib collapses – End of Test –
<u>Note(s):</u>	No ignition or burning of the sample occurred during the entire test period

Table 4.4.1: Observations recorded during the **SANS 10177-11** test

The test installation in the **SANS 10177-11** facility prior to ignition of the two Fire Source cribs and after the test was concluded is shown in Figure 4.1.1 and 4.1.8 respectively.



Figure 4.4.1: Test installation prior to ignition of the two Fire Source cribs



Figure 4.4.2: Material melting and bubble forming behind Crib



Figure 4.4.3: Coagulation of material behind Cribs



Figure 4.4.4: Coagulation of material exposing sheeting



Figure 4.4.5: Molten material starting to flow down



Figure 4.4.6: Heat damage visible on horizontally installed material



Figure 4.4.7: Cribs starting to collapse – No ignition occurred



Figure 4.4.8: Test installation after the **SANS 10177-11 (V)** test was concluded

## 5. DISCUSSION OF RESULTS

The product classification when tested in accordance with the **SANS 10177 – Part 5** test protocol is:

🔥 **IsoBoard (25 – 80 mm) » B (Combustible)**

The provisional classification for the various thicknesses when tested in accordance with **SANS 10177 – Part 10** is:

🔥 **25 mm IsoBoard » B/ B1/ 2**

🔥 **30 mm IsoBoard » B/ B1/ 2**

🔥 **40 mm IsoBoard » B/ B1/ 2**

🔥 **50 mm IsoBoard » B/ B1/ 2**

🔥 **80 mm IsoBoard » B/ B1/ 2**

As a result of the outcome obtained from the **SANS 10177 – Part 10** tests it was decided to use the worst case scenario (most material), the 80 mm-thick, **IsoBoard** panels for evaluation in the **SANS 10177 – Part 11, Horizontal and Vertical**, tests to be sufficiently representative of all lesser thicknesses within the product range.

The classification in terms of **SANS 428** for the 80 mm-thick **IsoBoard** when tested in accordance with the **SANS 10177 – Part 11, Horizontal (H) and Vertical (V)**, test protocols are:

🔥 **80 mm IsoBoard » B/ B1/ 2/ H & V (SP and USP)**

## 6. CONCLUSIONS

The **IsoBoard** product range, which includes all thicknesses from 25 mm up to 80 mm, as supplied by **Isofoam South Africa (Pty) Ltd** is classified as follows in terms of **SANS 428**:

Classification according to **SANS 428**:

 **IsoBoard (25 – 80 mm) » B/ B1/ 2/ H & V (SP and USP)**

The above results does not relate to fire resistance. In instances where fire resistance is a requirement, this property needs to be determined in terms of **SANS 10177-2**.





## ANNEXURE "A"

<b>– Company Information –</b>		
<b>Company Name:</b>	Isofoam South Africa (Pty) Ltd.	
<b>Company Registration Nr.:</b>	95/03958/07	
<b>Company VAT Nr.:</b>	4140154644	
<b>Core Business Activities:</b>	Manufacturing & Sales	
<b>Physical Address:</b>	23 Kenwill Drive, Okavango Park, Brackenfell, 7560	
<b>Postal Address:</b>	P O Box 1002 Cape Gate 7562	
<b>Contact details</b>		
Telephone number:	021 983-1140	
Facsimile number:	021 981-6099	
Cellphone number:	082 815 0994 / 082 347 0186	
Email address:	<a href="mailto:gm@isoboard.com">gm@isoboard.com</a>	
<b>Name of Contact Person</b>		
Technical:	Conrad Smith / Mark Russell	
Financial:	Beth Hewitt-Coleman	
<b>– Test information &amp; Sample/Product Description –</b>		
<b>Type of Test:</b>		
<b>Sample/Product Name:</b>		
<b>Manufacturing Date:</b>		
<b>Batch/Product Number:</b>		
<b>Sample/Product Description:</b>	<p><i>(Short description of sample or product submitted for testing)</i></p>	

This report is the property of **FIRELAB cc**. The Test Report and results only relate to the product(s) and/or sample(s) submitted for testing as identified in Section 2 and Annexure "A" and do not apply to any similar product(s) or sample(s) that has not been tested. This Test Report shall not be reproduced except in full, without written approval from **FIRELAB** and is only valid for 5 years or until there is change to the product composition, manufacturing process or previously approved supplier(s). The validity of this report may be extended by a validation certificate issued by **FIRELAB** upon verification of the product(s) or sample(s).



# FIRELAB


**Order No (FGR):** 700320  
**Date:** 03/06/2015  
**Page:** 1

**Client Details:**  
**Client Name:** CSIR  
**Order No:** 082 305 8559  
**Tel No:**  
**Fax No:**  
**Contact Name:** KOBUS STRYDOM

**Delivery Details:**  
**Required On:** 2015/06/03 12:00:00  
**Del Method:** COLLECT  
**From/To:**  
 35 Venturie Crescent, Hennops Park  
 Centurion  
 Pretoria

**RDC Details**  
**Phone:** +27 (012) 653 8204  
**Fax:** +21 (012) 653 0282  
**Email:** northsales@isoboard.com  
**Consultant:** Gauteng Sales  
 35 Venturie Crescent  
 Hennops Park  
 Centurion

## Requisition GTN-SAM



Item	Wh	Brd Qty	LenOrd	LenChg	W(mm)	T(mm)	m2	m3
ISOBOARD	GTN-FGR	2	8.00	8.00	600	25	9.60	0.240
ISOBOARD	GTN-FGR	2	8.00	8.00	600	30	9.60	0.290
ISOBOARD	GTN-FGR	2	8.00	8.00	600	40	9.60	0.380
ISOBOARD	GTN-FGR	2	8.00	8.00	600	50	9.60	0.480
ISOBOARD TI	GTN-FGR	2	8.00	8.00	600	80	9.60	0.770
ISOBOARD TI	GTN-FGR	30	6.00	6.00	600	80	108.00	8.640
ISOBOARD TI	GTN-FGR	10	4.00	4.00	600	80	24.00	1.920
							180.00	12.72

**Generated by: Mari-Louise Har**

**Other Requirements:**

**Short Edge:** SE  
**Finish:** Plain  
**Application:** OTH

**Long Edge:** TG  
**Laminated:** N

**Comments:**

Based On Sales Quotations 529758.