

LITTLEHAMPTON HARBOUR BOARD

LOCAL NOTICE TO MARINERS

No. 4 of 2004

**SHOAL AT ENTRANCE TO LITTLEHAMPTON
HARBOUR**

Mariners are advised that a large shoal has developed on the Western side of the narrows adjacent to the beach edging.

This has been caused by over topping of the beach into the navigational channel

Mariners are advised on entering Littlehampton Harbour, when safe to do so, navigate to the starboard side of the channel, just prior to reaching the area of the Eastern Pier.

Warning Notices will be sited at the commencement of the shoal for both Northerly and Southerly traffic.

Vessels can request updates of the position and size of the shoal, either by telephone on 01903-721215 or via VHF Channel 71.

C P Hitchcock
Harbour Master
7 April 2004