

# Roofing **W**arehouse

## EPDM Roof Repair



## Membrane repair

When it comes to repairing damaged EPDM, it couldn't be easier.

If the EPDM membrane is punctured, it is a simple procedure to make a waterproof repair.



Mark the area around the puncture at least 100mm in all directions.



Prime the marked area with Quickprime plus and a scrubber pad.



Cuts and punctures in the membrane should be repaired with cured cover strip. Cut out a piece of cover strip tape or FormFlash 75mm larger than the puncture and round off the corners. Remove the backing paper and apply over the puncture. Roll with the silicon hand roller.

