

96-D Allen Boulevard Farmingdale, New York 11735-5626 USA Tel. +1 (631) 293-8944 Fax +1 (631) 293-8956 e-mail: info@govmark.com

Page 1

Received: 11/1	2/2013 Completed: 11/13/2013	Letter: L	BG	P.O.#:	Test Report #:		2-99529-0-
Client's Identification	Style: Ultima Pro. Content: Poly	yester.					
	aime Sherman Jltraflex Systems Inc.	<u> </u>		Key Tes	t: CA 1237 Sm		155
1	578 Sussex Tpk., Bldg. #4 kandolph, NJ 07869				: 1-(973)-627-8608 : 1-(973)-627-8506	Ext:	

PC: 1H /jd

TEST PERFORMED: California Fire Marshal Title 19: Section 1237 (Proposed Revision 8/9/93) Fire Resistance; Small Scale Test - EXTERIOR MATERIALS QUALIFICATION

RESULTS REPORTED:

(x) Initially

[] After 72 hours water leaching

[] After 100 hours weathering

RESULTS:	Specimen #		Afterflame (seconds)	Afterglow (seconds)	Char Length (inches)
Warp:	1		0	0	4.4
	2		0	0	4.5
	3		0	0	4.6
İ	4		0	0	3.8
	5		0	0	4.0
		Avg:	0		
Fill:	6		0	0	5.1
	7		0	0	5.4
	8		0	0	4.7
	9		0	0	5.3
	10		0	0	5.3
		_			
1		Ava:	0		

APPROXIMATE WEIGHT OF MATERIAL (as measured by Govmark): 14.3 oz/yd²

ACCEPTANCE CRITERIA:

Afterflame: 4.0 seconds maximum avg for length or width

(see Note #2 below)

Char Length: 6.0" maximum for any individual specimen

Notes:

- 1. An asterisk (*) next to any char length measurements indicates that a part of the char length is melt away due to heat from the flame source and not from propagating flame. Therefore, the sample submitted meets the requirements of Title 19 - California Code of Regulations, Section 1237 and 1237.1 for materials weighing less than 4 oz/yd2.
- 2. Afterglow is required to be reported; however, it is not factored into the Acceptance Criteria.

(Page 1 of 2)



96-D Allen Boulevard Farmingdale, New York 11735-5626 USA Tel. +1 (631) 293-8944 Fax +1 (631) 293-8956 e-mail: info@govmark.com

Page 2

Received:11/12	2/2013 Completed: 11/13/2013	Letter: L	BG	P.O.#:	Test Report #:	2-99529-0-
Client's Identification	Style: Ultima Pro. Content: Pol	yester.	•			
Tested For: Jaime Sherman				155		
Ultraflex Systems Inc. 1578 Sussex Tpk., Bldg. #4 Randolph, NJ 07869					Tel: 1-(973)-627-8608 Fax: 1-(973)-627-8506	Ext:

CONCLUSION: Based on the above Results and Acceptance Criteria, the item tested:

[] Does not comply [x] Complies;

REMARKS: None.

NOTE: In August 1993 the State Fire Marshal issued a proposed revision, which permitted a maximum average afterflame of 4.0 seconds. This proposed revision was honored by the subsequent State Fire Marshal until approximately February 2004, at which time the State Fire Marshal's office reverted to the unrevised rule of 2.0 seconds maximum average for exterior fabric.

In a conversation with the latest California State Fire Marshal on August 9, 2007, it was learned that the proposed 1993 revision is now back in effect. In addition to allowing 4 seconds Afterflame rather than 2 seconds, the proposed revision provides for testing of 10 specimens, rather than 6 specimens. This information has again been verified current per an August 2013 correspondence with the California State Fire Marshall.

CERTIFICATION: I certify that the above results were obtained after testing specimens in accordance with the procedures and equipment specified by California Fire Marshal Title 19: Section 1237 (Proposed Revision 8/9/93).

NOV 1 5 2013

AUTHORIZED SIGNATURE

THE GOVMARK ORGANIZATION, INC.

q6/

MS. PHYLLIS PETTIT

(Page 2 of 2)