

SAFETY BULLETIN

Hotpoint/Indesit/Creda Brands Safety Concern

Affected tumble dryers



Condenser and vented dryers

Excess fluff in contact with heat

Following Whirlpool's acquisition of the Hotpoint/Indesit brands, Indesit Company has closely reviewed the safety of its product portfolio.

As part of this review the company has identified a potential concern with two types of tumble dryers manufactured between April 2004 and September 2015. In some rare cases, excess fluff can come into contact with the heating element and present a risk of fire. The affected brands are:

- Hotpoint
- Indesit
- Creda

An active customer outreach and service action plan is in place for an engineer to visit and carry out a modification, taking approximately one hour. Please visit the hotpoint website below for details

<https://safety.hotpoint.eu>

Important: Additional Information

The company say that you may continue to use your tumble dryer whilst waiting for the modification, however do not leave your dryer unattended during operation. As an extra precaution do not leave your house or leave the dryer on whilst asleep. Additionally, you should check and clean the filter after every cycle and ensure proper dryer venting, as directed in the original operating manual.