Material Safety Data Sheet

A		L Caranaga and Talanka and November		
Manufacturer's name UV Group PIc		Emergency Telephone Number 011 44 208 5568866		
Address		Telephone Number for Information 011	Telephone Number for Information 011 44 208 5568866	
20 RIGG APPROACH		Date Prepared 11/0	1/2008	
London E10 7QN United Kingdom		Signature of Preparer (optional)	ional) D.B.Selkus	
Section II – IMPORTANT COMPONENTS				
DESCRIPTION				
Wrightline - wood veneer re-co	onstituted to pe	erfection		
Genuine wood veneers laminated	d together with	Urea Formaldehyde Glue and re	e-sliced	
Permissible Exposure Concentration		•		
Not Regulated				
Section III—Physical Data				
Boiling Point	N/A	Specific Gravity (H ₂ 0 = 1)	N/A	
Vapor Pressure (mm Hg)	N/A	Melting Point	N/A	
Vapor Density (AIR = 1)	N/A	Evaporation Rate (Butyl Acetate = 1)	N/A	
Solubility in Water	N/A		l	
Appearance and Odor	Slight if an	у		
Section IV—Fire and Explosion Hazard D				
Flash Point (Method Used)	N/A			
Extinguishing Media	Water, Foam, 0	CO2		
Special Fire Fighting Procedures	, ,			
Firefighters should wear self-cor	ntained breathi	ng annaratus to avoid inhalation	of smoke or vanors	
Unusual Fire and Explosion Hazards	Training Broating		Tor official or Taporo	
None Known				
Section V—Reactivity Data				
Stability	Stable			
Hazardous Decomposition or Byproducts	ko & Fire if ion	ited. Acrid and choking fumes n	nav also he liberated	
Wear approved self-contained br			iay also be liberated.	
	Will not occur			
Hazardous	Onen flame and ignition			
Hazardous Polymerization		Open flame and ignition		
Hazardous		Open flame and ignition		

Wear Gloves, goggles and approved masks. Flush skin and eyes with clean water and consult a doctor

Section VII—Precautions for Safe Handling and Use			
Steps to Be Taken in Case Material Is Released or Spilled			
Sweep up and place in closed container. Wear a	dust mask if dust is created		
Waste Disposal Method			
Incinerate in approved incinerator or dispose of i federal regulations	n a chemical dump in accordance with local state &		
Section VIII - Special Protection Information			
Respiratory Protection (Specify Type) Dust mas	tion (Specify Type) Dust masks recommended when machining		
Ventilation Ensure	Ensure adequate ventilation		
Protective Gloves Leather Gloves Recommended	Eye Protection Goggles Recommended		
Section IX – Special Precautions			
Precautions to be taken in handling and storing			

Use according to instructions or existing practices

Store in a cool dry place
Other Precautions