KOGANEI

http://www.koganei.co.jp





Compliance Light

In addition to automatically aligning errors with the position of workpiece insertion, Compliance ight can be used for press fitting processes.

> **Compliance Light** CPL70F (parallel type)

Mounting plate

Flat type air hand AFDPG-8

Improves process during workpiece insertion and press fitting

Lightweight and compact

2 types: Parallel and swing

High rigidity and withstand load capacity The parallel type can be used as a press fitting base

* Please purchase the installation plate separately.

4 size variations

■34 mm [1.339 in.], **■54 mm** [2.126 in.],

■70 mm [2.756 in.], ■90 mm [3.543 in.]

NEW Greater retaining force supports high-speed conveyance by robots



NEW Increased variations!

Specifications of the improved retaining force

 More than double the retaining force compared to standard specifications

Perfect for high-speed conveyance

CPLH90F



Clean system specifications

Class 5 equivalent cleanliness





X

Parallel type Range of movement: X, Y, and θ

The parallel type corrects positional errors when inserting workpieces and press fitting, and when handling workpieces in the X, Y, and θ axes.

- In addition to being perfect for automatically aligning error with the workpiece insertion, the parallel type can be used as a press fitting pedestal
- Perfect for robot hands due to its lightweight design
- ullet Parallel type with a range of movement of X, Y, and ullet
- High rigidity and withstand load
- No centripetal force can be selected for all variations (Option: -N)





0

Explanation of operation


• When applying air pressure

Steel balls for positioning are pressed by the internal piston so that the unit and plate maintain a centered position.

• When not applying air pressure (if with centripetal force) The centripetal force of the restraining rings in the unit and plate maintain the center by acting in the directions of the X, Y, and θ axes.


Centripetal force: For Compliance Light, the restraining rings provide a force of 3 to 5 N [0.674 to 1.124 lbf.] (when movement is 0.5 mm [0.02 in.]) that acts to maintain the center.

This force is called "centripetal force".





P=0.5MPa	CPL34F	CPL54F	CPL70F	CPL90F
 Retaining force while applying air pressure 	7 N	18 N	42 N	67 N
Maximum load capacity	1kg	2kg	4kg	6kg
•Size variations	□34mm	□54mm	□70mm	□90mm
	* D. I			. H



^{*} Retaining force, according to Koganei measuring methods (reference value)

NEW


Specifications of the improved retaining force CPLH F

Parallel type

pe Page 14-

- More than double the retaining force when applying air pressure compared to standard specifications
- Perfect for the high-speed conveyance by robots due to greater retaining force

P=0.5MPa	CPLH34F	CPLH54F	CPLH70F	CPLH90F
• Retaining force while applying air pressure	24 N	64 N	115 N	140 N
 Maximum load capacity 	1kg	2kg	4kg	6kg
•Size variations	□34mm	□54mm	□70mm	□90mm



^{*} Retaining force, according to Koganei measuring methods (reference value)


NEW

Clean system specifications CS-CPL F Paral

Page 17→

- Just add a dust collection port and use clean grease to be perfect for use in clean rooms!
- Class 5 equivalent cleanliness (FED-STD Class 100 equivalent)

P=0.5MPa	CS-CPL34F	CS-CPL54F	CS-CPL70F	CS-CPL90F
 Retaining force while applying air pressure 	7 N	18 N	42 N	67 N
Maximum load capacity	1kg	2kg	4kg	6kg
•Size variations	□34mm	□54mm	□70mm	□90mm





^{*} Retaining force, according to Koganei measuring methods (reference value)

Swing type Range of movement: x, y, z, θ , and α

The swing type corrects positional errors when inserting workpieces and press fitting, and when handling workpieces in the X, Y, Z, θ , and α axes.

- Perfect for automatically aligning error with the workpiece
- Perfect for robot hands due to its lightweight design
- Swing type with a range of movement of X, Y, Z, θ , and α
- No centripetal force can be selected for all variations (Option: -N)





Explanation of operation

• When applying air pressure

Steel balls for positioning are pressed by the internal piston so that the unit and plate maintain a centered

• When not applying air pressure (if with centripetal force) The centripetal force of the restraining rings in the unit and plate maintain the center by acting in the directions of the X, Y, θ , and α axes. The direction of the Z axis operates as a buffer via springs.

Glossary


Centripetal force: For Compliance Light, the restraining rings provide a force of 3 to 5 N [0.674 to 1.124 lbf.] (when movement is 0.5 mm [0.02 in.]) that acts to maintain the center.

This force is called "centripetal force".

	· ·	
Air pressure applied Locked	Air pressure not applied Unlocked	Air pressure not applied Unlocked
Positioning error		
Beginning of workpiece insertion	Error correction functioning	Completion of workpiece insertion

■ Variations Size	□34mm	□54mm	□70mm	□90mm
Standard specifications CPL□S	\bigcirc		\bigcirc	\circ
Specifications of the improved retaining force CPLH S	•	•	•	•
Clean system specifications CS-CPL S	•	•	•	•

P=0.5MPa	CPL34S	CPL54S	CPL70S	CPL90S
 Retaining force while applying air pressure 	7 N	20 N	38 N	60 N
Maximum load capacity	1kg	2kg	4kg	6kg
•Size variations	□34mm	□54mm	□70mm	□90mm




^{*} Retaining force, according to Koganei measuring methods (reference value)

Specifications of the improved retaining force CPLH S swing type

Page 23-

- More than double the retaining force when applying air pressure compared to standard specifications
- Perfect for the high-speed conveyance by robots due to greater retaining force

P=0.5MPa	CPLH34S	CPLH54S	CPLH70S	CPLH90S
•Retaining force while applying air pressure	24 N	64 N	115 N	145 N
 Maximum load capacity 	1kg	2kg	4kg	6kg
•Size variations	□34mm	□54mm	□70mm	□90mm




^{*} Retaining force, according to Koganei measuring methods (reference value)

Clean system specifications CS-CPL S swing type

Page 26→

- Just add a dust collection port and use clean grease to be perfect for use in clean rooms!
- Class 5 equivalent cleanliness (FED-STD Class 100 equivalent)

P=0.5MPa	CS-CPL34S	CS-CPL54S	CS-CPL70S	CS-CPL90S
 Retaining force while applying air pressure 	7 N	20 N	38 N	60 N
 Maximum load capacity 	1kg	2kg	4kg	6kg
•Size variations	□34mm	□54mm	□70mm	□90mm



^{*} Retaining force, according to Koganei measuring methods (reference value)

Safety Precautions (Air Cylinders and General Actuators)

Always read these precautions carefully before use.

Before selecting and using the product, please read all the Safety Precautions carefully to ensure proper product use.

The Safety Precautions shown below are to help you use the product safely and correctly, and to prevent injury or damage to you, other people, and assets beforehand. Follow the Safety Precautions for: ISO4414 (Pneumatic fluid power-Recommendations for the application of equipment to transmission and control systems), JIS B 8370 (Pneumatic system regulations)

The directions are ranked according to degree of potential danger or damage: "DANGER!," "WARNING!," "CAUTION!," and "ATTENTION!"

⚠ DANGER	Expresses situations that can be clearly predicted as dangerous. If the noted danger is not avoided, it could result in death or serious injury. It could also result in damage or destruction of assets.
⚠ WARNING	Expresses situations that, while not immediately dangerous, could become dangerous. If the noted danger is not avoided, it could result in death or serious injury. It could also result in damage or destruction of assets.
⚠ CAUTION	Expresses situations that, while not immediately dangerous, could become dangerous. If the noted danger is not avoided, it could result in light or semi-serious injury. It could also result in damage or destruction of assets.
ATTENTION	While there is little chance of injury, this content refers to points that should be observed for appropriate use of the product.

■This product was designed and manufactured as parts for use in General Industrial Machinery.

- In the selection and handling of the equipment, the system designer or other person with fully adequate knowledge and experience should always read the Safety Precautions, Catalog, Owner's Manual and other literature before commencing operation. Making mistakes in handling is dangerous.
- After reading the Owner's Manual, Catalog, etc., always place them where they can be easily available for reference to users of this product.
- If transferring or lending the product to another person, always attach the Ownerr's Manual, Catalog, etc., to the product where they are easily visible, to ensure that the new user can use the product safely and properly.
- The danger, warning, and caution items listed under these "Safety Precautions" do not cover all possible cases. Read the Catalog and Owner's Manual carefully, and always keep safety first.

/\ DANGER

- Do not use the product for the purposes listed below:
 - 1. Medical equipment related to maintenance or management of human lives or bodies.
 - 2. Mechanical devices or equipment designed for the purpose of moving or transporting people.
 - 3. Critical safety components in mechanical devices.
 - This product has not been planned or designed for purposes that require advanced stages of safety. It could cause injury to human life.
- Do not use the product in locations with or near dangerous substances such as flammable or ignitable substances. This product is not explosion-proof. It could ignite or burst into flames.
- When mounting the product and workpiece, always firmly support and secure them in place. Dropping or falling the product or improper operation could result in injury.
- Never attempt to remodel the product. It could result in abnormal operation leading to injury.
- · Never attempt inappropriate disassembly, or assembly of the product relating to its basic inner construction, or to its performance or functions. It could result in injury.
- Do not splash water on the product. Spraying it with water, washing it, or using it underwater could result in malfunction of the product leading to injury.
- While the product is in operation, avoid touching it with your hands or otherwise approaching too close. In addition, do not make any adjustments to the interior or to the attached mechanisms (disconnection of piping tubes).
 - The actuator can move suddenly, possibly resulting in injury.

WARNING

- Do not use the product in excess of its specification range. Such use could result in product breakdowns, functions to stop, and damage. or drastically reduce the operating life.
- Before supplying air to the product and before starting operation, always conduct a safety check of the area of machine operation. Unintentional supply of air or electricity could possibly result in injury caused by contact with moving
- Always check the catalog and other reference materials for correct product piping. Improper piping creates the risk of damage to and abnormal operation of the actuator.

- Do not throw the product into fire. The product could explode and/or release toxic gases.
- Do not sit on the product, place your foot on it, or place other objects on it.
 - Accidents such as falling could result in injury. Dropping or toppling the product may result in injury, or it might also damage or break it, resulting in abnormal or erratic operation, runaway, etc.
- When conducting any kind of operation for the product, such as maintenance, inspection, repair, or replacement, always turn off the air supply completely and confirm that residual pressure inside the product or in piping connected to the product is zero before proceeding.
 - In particular, be aware that residual air will still be in the air compressor or air storage tank. The actuator could abruptly move if residual air pressure remains inside the piping, causing injury.
- Do not use the actuator for equipment whose purpose is absorbing the shocks and vibrations of mechanical devices. It could break and possibly result in injury or in damage to mechanical devices.
- Use within the maximum load capacity. Using the product beyond the maximum load capacity may damage equipment or cause personal injury.
- Use safety circuits or system designs to prevent damage to machinery or injury to personnel when the machine is shut down due to emergency stop or electrical power failure.
- In initial operations after the equipment has been idle for 48 hours or more, or has been in storage, there is a possibility that contacting parts may stick, resulting in equipment operation delays or sudden movements. For these initial operations, always run a test operation before use to check that operating performance is normal.
- Do not use the product near the ocean, in direct sunlight, near mercury vapor lamps, or near equipment that generates ozone. Deterioration of rubber parts caused by ozone may reduce performance and functions or stop functions.
- Because Koganei products may be used under a wide variety of conditions, decisions concerning conformance with a particular system should be made upon the careful evaluation by the person in charge of system design. Assurances concerning expected system performance and safety are the responsibility of the designer who decides system conformity. Be sure to use the latest catalogs and technical materials to study and evaluate specification details, to consider the possibility of machine breakdown, and to configure a system that ensures fail-safe safety and reliability.

• Do not use the product in locations subject to direct sunlight (ultraviolet radiation), in locations with dust, salt, or iron particles, or in locations with media and/or ambient atmosphere that include organic solvents, phosphate ester type hydraulic oil, sulfur dioxide gas, chlorine gas, acids, etc. Such uses could lead to loss of functions within a short period, sudden degradation in performance, or reduced operating life. For details on materials used in the product, refer to the description of materials used in major parts.

/\ CAUTION

- When installing the product, leave room for adequate working space around it. Failure to ensure adequate working space will make it more difficult to conduct daily inspections or maintenance, which could eventually lead to system shutdown or damage to the product.
- Do not scratch, dent, or deform the actuator by climbing on the product, using it as a scaffold, or placing objects on top of it. It could result in damaged or broken a product that results in operation shutdown or degraded performance.
- Always post an "operations in progress" sign for installations, adjustments, or other operations, to avoid unintentional supplying of air, electrical power, etc. Such accidental supplies may cause electric shock or sudden activation of the product that could result in physical injury.
- Using extremely dry air with a dew point lower than -20°C [-4°C], may affect the quality of the lubricating oil used. This creates the risk of degraded performance, loss of function, or other problems.

ATTENTION

- · When considering the possibility of using this product in situations or environments not specifically noted in the Catalog or Owner's Manual, or in applications where safety is an important requirement such as in an airplane facility, combustion equipment, leisure equipment, safety equipment, and other places where human life or assets may be greatly affected, take adequate safety precautions such as an application with enough margins for ratings and performance or failsafe measure.
 - Be sure to consult us about such applications.
- Use a protective cover, etc., to ensure that human bodies do not come into direct contact with the operating portion of mechanical devices, etc.
- Do not control in a way that would cause workpieces to fall during power failure.
 - Take control measures so that they prevent the workpieces, etc., from falling during power failure or emergency stop of the mechanical devices.
- When handling the product, wear protective gloves, safety glasses, safety shoes, etc., to keep safety.
- When the product can no longer be used, or is no longer necessary, dispose of it appropriately as industrial waste.
- Pneumatic equipment can exhibit degraded performance and function over its operating life. Always conduct daily inspections of the pneumatic equipment, and confirm that all requisite system functions are satisfied, to prevent accidents from happening.
- For inquiries about the product, contact your nearest Koganei sales office or Koganei overseas department. The address and telephone number is shown on the back cover of this catalog.

$/!\setminus$ OTHERS

- Always observe the following items.
 - 1. When using this product in pneumatic systems, always use genuine KOGANEI parts or compatible parts (recommended
 - When conducting maintenance and repairs, always use genuine KOGANEI parts or compatible parts (recommended parts).
 - Always observe the required methods.
 - 2. Do not attempt inappropriate disassembly or assembly of the product relating to basic configurations, or its performance or functions.

Koganei cannot be responsible if these items are not properly observed.

Warranty and General Disclaimer

- 1. Warranty Period
 - The warranty period for Koganei products is 1 year from the date of delivery.
 - *However, some products have a 2-year warranty; contact your nearest Koganei sales office or the Koganei overseas department for details.
- 2. Scope of Warranty and General Disclaimer
- (1) When a product purchased from Koganei or from an authorized Koganei distributor or agent malfunctions during the warranty period in a way that is attributable to Koganei's responsibility, Koganei will repair or replace the product free of charge. Even if a product is still within the warranty period, its durability is determined by its operation cycles and other factors. Contact your nearest Koganei sales office or the Koganei overseas department for details.
- (2) The Koganei product warranty covers individual products. Therefore, Koganei is not responsible for incidental losses (repair of this product, various expenses required for replacement, etc.) caused by breakdown, loss of function, or loss of performance of Koganei products.
- (3) Koganei is not responsible for any losses or for any damages to other machinery caused by breakdown, loss of function, or loss of performance of Koganei prod-
- (4) Koganei is not responsible for any losses due to use or storage of the product in a way that is outside of the product specifications prescribed in Koganei catalogs and instruction manuals, and/or due to actions that violate the mounting, installation, adjustment, maintenance or other safety precautions.
- (5) Koganei is not responsible for any losses caused by breakdown of the product due to factors outside the responsibility of Koganei, including but not limited to fire, natural disaster, the actions of third parties, and intentional actions or errors by the purchaser.



General precautions

Piping

Before performing piping work on the product, thoroughly flush the inside of the pipes (blow out with compressed air). Machining chips, sealing tape, rust and other debris remaining from the piping work may result in air leaks and malfunctions. The dust collection port for the clean system specifications is a counterbore connection port. When piping and mounting, make sure that the connection port for the lock is correct.

Air supply

- Use air as the medium. For the use of any other medium, consult your nearest Koganei sales office.
- 2. Air used for the product should be clean air that contains no degraded compressor oil, etc. Install an air filter (filtration of 40 μ m or less) near the product to remove collected liquid or dust. Also drain the air filter periodically. If liquid or dust gets into the product, it may cause defective operation.

Lubrication

- The cylinder can be used without lubrication, however, if lubrication, such as a lubricator, is used, use turbine oil type 1 (ISO VG32) or an equivalent. Avoid using spindle oil or machine oil.
- Never apply lubrication to the sliding parts of the swing type. Doing so may cause defective operation.
- **3.** Do not apply lubricants in clean system specifications. Applying lubrication may cause malfunctions.

Environment

- 1. Cover the unit when using it in locations where it might be subject to excessive dust, dripping water, dripping oil, etc.
- Do not use the product in environments which may be corrosive. Using the cylinder in these types of environments may result in damage or defective operation.
- 3. Do not use it in excessively dry conditions.
- 4. Do not use the cylinder if the ambient temperature is over 60°C [140°F], doing so may result in damage or defective operation. Also, consider anti-freezing measures if the temperature is less than 5°C [41°F], because moisture may freeze and result in damage or defective operation.

Handling

- Confirm that there is no residual pressure in the product before starting maintenance work.
- Displacement should not exceed the allowed range of movement in any direction. It could result in damaged or broken a product that results in operation shutdown or degraded performance.
- 3. To lock or unlock the function for error correction (compliance), switch between applying and not applying air pressure. When inserting or pushing, do so in an unlocked state with no air pressure applied. When moving, do so in a locked state with air pressure applied. Moreover, install a shock absorber, etc., where the movement comes to a standstill to ensure as smooth a stop as possible. Sudden stops may cause the lock to disengage, and reduce the centripetal accuracy.
- 4. Use within the range for the maximum load capacity. Using this unit while exceeding the maximum load capacity may cause wear or degradation to the sliding parts.
- 5. The value for the allowable load is a static load. Treat it as a temporary load in a stationary state. Ensure that there are sufficient allowances if the unit is subjected to impacts. When press fitting, use a load of 1/10 or less of the value for the allowable load.
- 6. The parallel type can also be used in a lower position. When using it in a lower position, use it on the center of the product and do not allow it to hang over. The mounted load should be less than the maximum load capacity.
- 7. The center position when pressure is applied to the plate and the

- center position when pressure is not applied may be misaligned.
- 8. Mount the product so that the center of gravity of the mounted load falls within the plate's external diameter, and do not operate with an overhanging load. Doing so may cause wear or degradation to the sliding parts.
- 9. For each product that does not have centripetal force (-N), the retaining force and the retaining moment are the same as the values indicated on the graph.

Installing

- Use this unit in a horizontal position when no air pressure is applied (unlocked). The mounting surface should be flat. If the cylinder twists or bends when mounted, not only will it be inaccurate, but there may be air leaks and defective operation.
- Note that if the product's mounting surface is scratched or dented it can adversely affect flatness.
- 3. Be sure that the unit and the mounting bolts are strong enough.
- 4. In cases where loosening of screws due to impact and/or vibration may be a factor, consider looseness prevention measures. Be careful that adhesive spreads out evenly. If the adhesive gets into the product, it may cause defective operation.
- Be careful that error correction (compliance) is not obstructed by piping and wiring when mounting hands, etc., to the mounting surface.


Repeatability

Move the plate, with no load and no air pressure applied, in any direction and measure the position at which the plate stops after applying air. Measure this 10 times and calculate the maximum deviation. The repeatability is the value with \pm appended to 1/2 of the calculated maximum deviation.

Repeatable angle accuracy

Unidirectional repeatability


Rotate the plate, with no load and no air pressure applied, in the same direction and measure the angle at which the plate stops after applying air. Measure this 10 times and calculate the maximum deviation. The repeatable angle accuracy is the value with \pm appended to 1/2 of the calculated maximum deviation.



Unidirectional repeatability

Bidirectional repeatability

Rotate the plate, with no load and no air pressure applied, laterally and measure the angle at which the plate stops after applying air. Measure this 10 times and calculate the maximum deviation. The repeatable angle accuracy is the value with \pm appended to 1/2 of the calculated maximum deviation.



Bidirectional repeatability


Handling Instructions and Precautions


Tightening torque


Fittings

Screw size	Tightening torque N·m [ft·lbf]
M3×0.5	0.7 [0.516]
M5×0.8	1.0 ~ 1.5 [0.738 ~ 1.106]

• Mounting a workpiece









• Installing the main unit

Standard specifications and clean system specifications



Specifications of the improved retaining force



Туре	Model	Bolt	Maximum tightening torque (N·m [ft·lbf])	A (mm [in.])	B (mm [in.])	C (mm [in.])	D (mm [in.])
	CPL34F		0.63 [0.465]	4.3 [0.169]			
	CPLH34F	M3×0.5			1 [0.039]	5.3 [0.209]	6 [0.236]
	CS-CPL34F						
	CPL54F						7 [0.276]
	CPLH54F	M5×0.8	3 [2.213]	5.2 [0.205]	1.5 [0.059]	6.7 [0.264]	10 [0.394]
Daniella Ltona	CS-CPL54F						7 [0.276]
Parallel type	CPL70F						8 [0.315]
	CPLH70F	M5×0.8	3 [2.213]	6.3 [0.248]	1.5 [0.059]	7.8 [0.307]	11 [0.433]
	CS-CPL70F						8 [0.315]
	CPL90F	M6×1		7 [0.276]		9 [0.354]	9 [0.354]
	CPLH90F		5.2 [0.205]		2 [0.079]		14 [0.551]
	CS-CPL90F						9 [0.354]
	CPL34S	M3×0.5	0.63 [0.465]	4.8 [0.189]	1 [0.039]	5.8 [0.228]	
	CPLH34S						6 [0.236]
	CS-CPL34S						
	CPL54S	M5×0.8			6.7 [0.264] 1.5 [0.059]	8.2 [0.323]	7 [0.276]
	CPLH54S		3 [2.213]	3 [2.213] 6.7 [0.264]			10 [0.394]
	CS-CPL54S						7 [0.276]
Swing type	CPL70S				1.5 [0.059]		8 [0.315]
	CPLH70S	M5×0.8	3 [2.213]	7.8 [0.307]		9.3 [0.366]	11 [0.433]
	CS-CPL70S						8 [0.315]
	CPL90S						9 [0.354]
	CPLH90S	M6×1	5.2 [0.205]	9.5 [0.374]	2 [0.079]	11.5 [0.453]	14 [0.551]
	CS-CPL90S						9 [0.354]

Cleanliness Evaluation (Compliance Light)

Cleanliness evaluation methods for current clean specification pneumatic equipment are not defined by JIS or other standards.

Because of this, Koganei devises its own independent measurement methods for cleanliness and evaluates accordingly.

1. Samples being measured (with suction from the dust collection port)

Parallel type	Load
CS-CPL34F	0.4kg
CS-CPL54F	0.8kg
CS-CPL70F	1.1kg
CS-CPL90F	1.1kg

Swing type	Load
CS-CPL34S	0.4kg
CS-CPL54S	0.8kg
CS-CPL70S	1.1kg
CS-CPL90S	1.1kg

2. Measurement procedure

2-1 Checking the volume of dust emission in the measurement system

Particles are measured in the clean bench (Figure 1) for 9 minutes without operating the samples in the clean bench (background measurement).

This confirms that, under the background measurement conditions, the number of particles measures 0 (zero).

2-2 Actual measurement

The samples are operated for 36 minutes and the total value of dust emission is measured for the latter 18 minutes.

2-3 Re-confirmation

The measurements in 2-1 are done again to re-check the dust emission in the clean bench.

2-4 Measurement value conversion

The total value of dust emission measured in the latter 18 minutes of 2-2 is converted to the value per 10 operations.

3. Measurement conditions

• Operating frequency: 1 Hz (air supply to compliance light ON-OFF)

• Applied air pressure: 0.5 MPa

• Suction conditions: Micro ejector: ME05

Primary side: 0.5 MPa air pressure applied

Usable tubes: ϕ 6

Particle counter used

Suction flow: 28.3 \(\ell \) /min (ANR) [1.000 ft 3/min (SCFM)]

Diameter of measured particles: 0.1 μ , 0.2 μ , 0.3 μ , 0.5 μ , 0.7 μ , 1.0 μ

4. Measurement results

• Measurement results after one million sample operations

(with suction from the dust collection port)

Parallel type: CS-CPL34F, CS-CPL54F,

CS-CPL70F, CS-CPL90F Swing type: CS-CPL34S, CS-CPL54S

Dust emission in the products above could not be

confirmed.

Swing type: Volume of dust emission for

CS-CPL70S, CS-CPL90S

The following graph shows the results.

Note: The results of dust emission in the graph are actual values measured under Koganei standards, and are not intended to be guaranteed values.





Figure 1: Outline of particle measuring device


● CS-CPL70S

Dust emission of each particle size (per 10 operations)



● CS-CPL90S

CS-CPI 90S Dust emission of each particle size (per 10 operations)



Standard specifications Parallel type



Specifications

	Basic type	CPL34F	CPL34F-N	CPL54F	CPL54F-N	CPL70F	CPL70F-N	CPL90F	CPL90F-N
Item			0.20		0.20	0. 2. 0.	0.2.0.1		0. 200. 10
Bore size	mm [in.]	6 [0.	236]	10 [0).394]	16 [0	.630]	20 [0).787]
Dimensions	mm [in.]	□34 [□	□1.339]	□54 [□	2.126]	□70 [□	2.756]	□90 [□	□3.543]
Height	mm [in.]	18 [0	.709]	22 [0).866]	25 [0	.984]	28 [1	.102]
Mass	g [oz.]	42 [1	.482]	130	[4.6]	250	[8.8]	460	[16.2]
Operating type					Single a	cting type			
Media					Α	ir			
Operating pressure	range MPa [psi.]				0.2 to 0.7 [29.0	000 to 101.500]			
Proof pressure	MPa [psi.]				1.05 [1	52.250]			
Operating temperature	range °C [°F]	0 to 60 [0 to 140.000]							
Diameter of connect	ion port mm [in.]	M3×0.	5 [0.02]			M5×0.8	8 [0.031]		
Lubrication	Cylinder part				Not re	quired			
Lubrication	Sliding part				Not re	quired			
Maximum load capa	city kg [lb.]	1 [2.	205]	2 [4	.410]	4 [8.	820]	6 [13	3.230]
Mayamant range	X — Y mm [in.]	±0.5	[0.02]	±1 [C	0.039]	±1.5 [0.059]	±2 [0	0.079]
Movement range	θ (twisting) $^{\circ}$	±	3			±	4		
Centripetal force (when mover	nent is 0.5 mm)Note1 N [lbf.]	3 [0.674]	0 [0]	5 [1.124]	0 [0]	5 [1.124]	0 [0]	3 [0.674]	0 [0]
Repeatability Note2 (in the direction of X and Y)	P=0.5MPa mm [in.]				±0.05	[0.002]			
Repeatable angle accuracy $^{\text{Note3}}$ (in the direction of θ)	P=0.5MPa Degrees	±0.05 [0.002] (unidirectional repeatability) ±0.05 [0.002] (unidirectional repeatability) ±0.1 [0.004] (bidirectional repeatability) ±0.1 [0.004] (bidirectional repeatability)						ľ repeatability) 0.004]	
Withstand load Note5	Pushing direction N [lbf.]	1580	[355]	2840	[638]	5150	[1158]	6670	[1499]
vviii istatiu ioau netee	Pulling direction N [lbf.]	[[bf.] 840 [188.8] 1480 [333] 2980 [670] 4880 [109						[1097]	

Note 1: Centripetal force: Indicates the force, with no load and no air pressure applied, that maintains the center position via the restraining ring.

Note 2: Repeatability: The maximum deviation of the position at which the plate, with no load and no air pressure applied, stops when air has been applied after moving it in any direction. For details, see page 7.

Note 3: Repeatable angle accuracy

Unidirectional repeatability

The maximum deviation of the angle at which the plate, with no load and no air pressure applied, stops when air has been applied after rotating it in the same direction. For details, see page 7.

Bidirectional repeatability

The maximum deviation of the angle at which the plate, with no load and no air pressure applied, stops when air has been applied after rotating laterally. For details, see page $\ensuremath{\mathbb{T}}$.

Note 4: The center position when air pressure is applied to the plate and the center position when air pressure is not applied may be misaligned.


: without centripetal force

Note 5: When press fitting, use a load of 1/10 or less of the value for the allowable load. For details, see page ①.

Note 6: Mount the product so that the center of gravity of the mounted load falls within the plate's external diameter, and do not operate with an overhanging load.


Note 7: For the Handling Instructions and Precautions, see page ①.

Order Codes




Direction of movement

• X, Y, and θ axes



Inner construction



Major parts and materials

No.	Model Name	CPL34F	CPL54F	CPL70F	CPL90F						
1	Unit	Aluminu	ım alloy (elec	troless nicke	l plated)						
2	Frame	Aluminu	ım alloy (elec	troless nicke	l plated)						
3	Plate	Aluminum alloy (electroless nickel plated)									
4	Piston	Aluminum alloy (anodized)									
<u></u>	Disk	Aluminum alloy (special anti-abrasion treated)									
6	Spacer	Stainless steel (heat-treated)									
7	Alignment pin	S	tainless steel	(heat-treated	d)						
8	Restraining ring		Stainle	ss steel							
9	Spring		Stainle	ss steel							
10	Parallel pin		Stainle	ss steel							
11	Steel ball	Steel									
12	Seal		Synthetic ru	ibber (NBR)							
13	Bolt	Stainless steel									

Graph (reference values)


· Centripetal force


* Centripetal force: Force that maintains the center position via the restraining ring in a condition in which no load and no air pressure is applied.


1N = 0.225 lbf.


1mm = 0.039 in.















Retaining force, Retaining moment Retaining force Retaining moment

- * Retaining force: Force that maintains the center position of the X and Y directions when air pressure is applied
- * Retaining moment: Force that maintains the center position of the θ direction when air pressure is applied












CPL34F CPL54F










Model Code	Α	В	С	D	Е	F	G	Ι	J	K	L	М	N	Р	Q	R
CPL34F	34 [1.339]	28 [1.102]	46 [1.811]	32 [1.260]	13 [0.512]	26 [1.024]	18 [0.709]	8.9 [0.350]	8.7 [0.343]	4 [0.157]	4.3 [0.169]	4.9 [0.193]	M3×0.5 [0.020]	3.4 [0.134]	3 [0.118]	4 [0.157]
CPL54F	54 [2.126]	44 [1.732]	72 [2.835]	52 [2.047]	21 [0.827]	42 [1.654]	22 [0.866]	10.5 [0.413]	10.9 [0.429]	5 [0.197]	5.2 [0.205]	5.2 [0.205]	M5×0.8 [0.031]	5.5 [0.217]	4 [0.157]	5 [0.197]

Model Code	S	Т	U	V	W	Х	Υ	Z
CPL34F	12 [0.472]	2 [0.079]	1.5 [0.059]	M3×0.5 [0.020]	6 [0.236]	4.3 [0.169]	4 [0.157]	1 [0.039]
CPL54F	20 [0.787]	2.5 [0.098]	1.5 [0.059]	M5×0.8 [0.031]	7 [0.276]	5.2 [0.205]	6 [0.236]	1.5 [0.059]

CPL70F CPL90F







Model Code	Α	В	С	D	Е	F	G	Н	J	K	L	М	N	Р	Q	R
CPL70F	70 [2.756]	58 [2.283]	92 [3.622]	70 [2.756]	30 [1.181]	60 [2.362]	25 [0.984]	11.3 [0.445]	13.1 [0.516]	6 [0.236]	6.3 [0.248]	5.5 [0.217]	M5×0.8 [0.031]	5.5 [0.217]	5 [0.197]	6 [0.236]
CPL90F	90 [3.543]	74 [2.913]	116 [4.600]	90 [3.543]	40 [1.575]	80 [3.150]	28 [1.102]	12.8 [0.504]	14.5 [0.571]	6 [0.236]	7 [0.276]	5.6 [0.220]	M5×0.8 [0.031]	6.6 [0.260]	6 [0.236]	7 [0.276]

Model Code	S	Т	U	V	W	Х	Υ	Z	AA	AB
CPL70F	34 [1.339]	2.5 [0.098]	1.5 [0.059]	M5×0.8 [0.031]	8 [0.315]	6.3 [0.248]	7 [0.276]	1.5 [0.059]	12 [0.472]	28 [1.102]
CPL90F	50 [1.969]	2.5 [0.098]	1.5 [0.059]	M6×1 [0.039]	9 [0.354]	7 [0.276]	7 [0.276]	2 [0.079]	12 [0.472]	38 [1.496]

Specifications of the improved retaining force Parallel type



Specifications

lkama	Basic type	CPLH34F	CPLH34F-N	CPLH54F	CPLH54F-N	CPLH70F	CPLH70F-N	CPLH90F	CPLH90F-N
Item	F 1	10.50	222	25.50		10.51	===1	=0.1	2001
Bore size	mm [in.]	16 [0	.630]	25 [0	0.984]	40 [1	.575]		.969]
Dimensions	mm [in.]	□34 [□	1.339]	□54 [□	2.126]	□70 [□	2.756]	□90 [□	□3.543]
Height	mm [in.]	25 [0	.984]	31 [1	.220]	36 [1	.417]	41 [1	.614]
Mass	g [oz.]	65 [2	2.29]	190	[6.70]	380 [13.40]	710 [25.04]
Operating type					Single ac	cting type			
Media					Α	ir			
Operating pressure	range MPa [psi.]				0.2 to 0.7 [29.0	000 to 101.500]			
Proof pressure	MPa [psi.]				1.05 [1	52.250]			
Operating temperature	range °C [°F]				0 to 60 [0 t	to 140.000]			
Diameter of connect	tion port mm [in.]	[in.] M3×0.5 [0.02] M5×0.8 [0.031]							
Lubrication	Cylinder part				Not re	quired			
Lubrication	Sliding part				Not re	quired			
Maximum load capa	city kg [lb.]	1 [2.	205]	2 [4	.410]	4 [8.	820]	6 [13	3.230]
Mayamant ranga	$X-Y \mod [in.]$	±0.5	[0.02]	±1 [C	0.039]	±1.5 [0.059]	±2 [0	0.079]
Movement range	$ heta$ (twisting) $^{\circ}$	±	3			±	:4		
Centripetal force (when mover	nent is 0.5 mm)Note1 N [lbf.]	3 [0.674]	0 [0]	5 [1.124]	0 [0]	5 [1.124]	0 [0]	3 [0.674]	0 [0]
Repeatability Note2	P=0.5MPa				.0.05	10,0001			
(in the direction of X and Y)	mm [in.]				±0.05	[0.002]			
Repeatable angle	P=0.5MPa	±0.1 [0.004] ±0.05 [0.002] (bidirectional repeatability)							
accuracy Note3 (in the direction of θ)	Degrees	(bidirectional	repeatability)		±0.0	5 [U.UU2] (DIdire	cuonai repeatat	ollity)	
Withstand load Notes	Pushing direction N [lbf.]	1580	[355]	2840	[638]	5150	[1158]	6670	[1499]
Withstand load Note5	Pulling direction N [lbf.]	840 [188.8]	1480	[333]	2980	[670]	4880	[1097]

Note 1: Centripetal force: Indicates the force, with no load and no air pressure applied, that maintains the center position via the restraining ring.

Note 2: Repeatability: The maximum deviation of the position at which the plate, with no load and no air pressure applied, stops when air has been applied after moving it in any direction. For details, see page ⑦.


Note 3: Repeatable angle accuracy: bidirectional repeatability

The maximum deviation of the angle at which the plate, with no load and no air pressure applied, stops when air has been applied after rotating laterally. For details, see page $\widehat{\mathcal{D}}$.

- Note 4: The center position when air pressure is applied to the plate and the center position when air pressure is not applied may be misaligned.
- Note 5: When press fitting, use a load of 1/10 or less of the value for the allowable load. For details, see page $\ensuremath{\mathbb{C}}$.
- Note 6: Mount the product so that the center of gravity of the mounted load falls within the plate's external diameter, and do not operate with an overhanging load.
- Note 7: For the Handling Instructions and Precautions, see page ?


Order Codes

· Specifications of the improved retaining force, parallel type




Direction of movement

• X, Y, and θ axes



Inner construction



Major parts and materials


No.	Model Name	CPLH34F	CPLH54F	CPLH70F	CPLH90F							
1	Unit	Aluminu	ım alloy (elec	troless nicke	l plated)							
2	Unit connection	Aluminu	ım alloy (elec	troless nicke	l plated)							
3	Frame	Aluminu	ım alloy (elec	troless nicke	l plated)							
4	Plate	Aluminum alloy (electroless nickel plated)										
<u></u>	Piston	Aluminum alloy (anodized)										
6	Lock piston	Steel (electroless nickel plated)										
7	Disk	Aluminum alloy (special anti-abrasion treated)										
8	Spacer	S	tainless steel	(heat-treated	d)							
9	Alignment pin	S	tainless steel	(heat-treated	d)							
10	Restraining ring		Stainle	ss steel								
11)	Spring		Piano	wire								
12	Parallel pin		Stainle	ss steel								
13	Steel ball	Steel										
14)	Seal		Synthetic ru	bber (NBR)								
15	Bolt	Stainless steel										


Graph (reference values)


· Centripetal force


* Centripetal force: Force that maintains the center position via the restraining ring in a condition in which no load and no air pressure is applied.

1N = 0.225 lbf.1mm = 0.039 in.











• Retaining force, Retaining moment Retaining force — Retaining moment

- * Retaining force: Force that maintains the center position of the X and Y directions when air pressure is applied
- * Retaining moment: Force that maintains the center position of the θ direction when air pressure is applied



印加圧力(MPa)


CPLH34F CPLH54F



CPLH34F	12 [0.472]	2 [0.079]	1.5 [0.059]	M3×0.5 [0.020]	6 [0.236]	4.3 [0.169]	4 [0.157]	1 [0.039]
CPLH54F	20 [0.787]	2.5 [0.098]	1.5 [0.059]	M5×0.8 [0.031]	10 [0.394]	5.2 [0.205]	6 [0.236]	1.5 [0.059]

S T U V W X Y Z

CPLH70F CPLH90F



Model Code	Α	В	С	D	Е	F	G	Н	J	K	L	М	N	Р	Q	R
CPLH70F	70 [2.756]	58 [2.283]	92 [3.622]	70 [2.756]	30 [1.181]	60 [2.362]	36 [1.417]	22.3 [0.878]	13.1 [0.516]	6 [0.236]	6.3 [0.248]	5 [0.197]	M5×0.8 [0.031]	5.5 [0.217]	5 [0.197]	6 [0.236]
CPLH90F	90 [3.543]	74 [2.913]	116 [4.600]	90 [3.543]	40 [1.575]	80 [3.150]	41 [1.614]	25.8 [1.016]	14.5 [0.571]	6 [0.236]	7 [0.276]	5.5 [0.217]	M5×0.8 [0.031]	6.6 [0.260]	6 [0.236]	7 [0.276]

Model Code	S	Т	U	V	W	Х	Υ	Z	AA	AB
CPLH70F	34 [1.339]	2.5 [0.098]	1.5 [0.059]	M5×0.8 [0.031]	11 [0.433]	6.3 [0.248]	7 [0.276]	1.5 [0.059]	12 [0.472]	28 [1.102]
CPLH90F	50 [1.969]	2.5 [0.098]	1.5 [0.059]	M6×1 [0.039]	14 [0.551]	7 [0.276]	7 [0.276]	2 [0.079]	12 [0.472]	38 [1.496]

Clean system specifications Parallel type



Specifications

Item	Basic type	CS-CPL34F	CS-CPL34F-N	CS-CPL54F	CS-CPL54F-N	CS-CPL70F	CS-CPL70F-N	CS-CPL90F	CS-CPL90F-N		
Bore size	mm [in.]	01.6	236]	10.00).394]	16.00	0.630]	20.10).787]		
Dimensions	mm [in.]]1.339]		2.126]				☐3.543]		
Height	mm [in.]	-	.709]		0.866]		0.984]	-	.102]		
Mass	g [oz.]	-	.482]		[4.6]		[8.8]	_	[16.2]		
Operating type	0. 1		-		Single ad	cting type			-		
Media					A	ir					
Operating pressure	range MPa [psi.]				0.2 to 0.7 [29.0	000 to 101.500]					
Proof pressure	MPa [psi.]				1.05 [1	52.250]					
Operating temperature	range °C [°F]				0 to 60 [0 t	o 140.000]					
Diameter of connect	ion port mm [in.]	M3×0.	5 [0.02]			M5×0.	8 [0.031]				
Labelantan	Cylinder part				N	О					
Lubrication	Sliding part				N	0					
Maximum load capa	city kg [lb.]	1 [2.	205]	2 [4	.410]	4 [8	.820]	6 [13	3.230]		
Marramantanana	X – Y mm [in.]	±0.5	[0.02]	±1 [0	0.039]	±1.5 [0.059]	±2 [0	0.079]		
Movement range	θ (twisting) $^{\circ}$	±	3			±	±4				
Centripetal force (when moven	nent is 0.5 mm)Note1 N [lbf.]	3 [0.674]	0 [0]	5 [1.124]	0 [0]	5 [1.124]	0 [0]	3 [0.674]	0 [0]		
Repeatability Note2 (in the direction of X and Y)	P=0.5MPa mm [in.]				±0.05	[0.002]					
Repeatable angle accuracy $^{\text{Note3}}$ (in the direction of θ)	P=0.5MPa Degrees		±0.2	2 [0.008] (bidired	ctional repeatab	ility)			0.004] repeatability)		
,	Pushing direction N [lbf.]	1580	[355]	2840	[638]	5150	[1158]	6670	[1499]		
Withstand load Note5	Pulling direction N [lbf.]	840 [188.8]	1480	[333]	2980	[670]	4880	[1097]		
Dust collection port	mm [in.]	M3×0.	5 [0.02]			M5×0.	8 [0.031]				
Cleanliness		Cla	ss 5 equivalent	(When vacuum	sucked via the	dust collection p	port. Based on k	Koganei standa	rds.)		


- Note 1: Centripetal force: Indicates the force, with no load and no air pressure applied, that maintains the center position via the restraining ring.
- Note 2: Repeatability: The maximum deviation of the position at which the plate, with no load and no air pressure applied, stops when air has been applied after moving it in any direction. For details, see page ①.
- Note 3: Repeatable angle accuracy: bidirectional repeatability

The maximum deviation of the angle at which the plate, with no load and no air pressure applied, stops when air has been applied after rotating laterally. For details, see page ①.

- Note 4: The center position when air pressure is applied to the plate and the center position when air pressure is not applied may be misaligned.
- Note 5: When press fitting, use a load of 1/10 or less of the value for the allowable load. For details, see page ⑦.
- Note 6: Mount the product so that the center of gravity of the mounted load falls within the plate's external diameter, and do not operate with an overhanging load.
- Note 7: For the Handling Instructions and Precautions, see page ①.


Order Codes

· Clean system specifications, parallel type




Direction of movement

· X, Y, and θ axes





Inner construction



Major parts and materials

No.	Model Name	CS-CPL34F	CS-CPL54F	CS-CPL70F	CS-CPL90F					
1	Unit	Aluminu	ım alloy (elec	troless nicke	l plated)					
2	Frame	Aluminu	ım alloy (elec	troless nicke	l plated)					
3	Plate	Aluminu	ım alloy (elec	troless nicke	l plated)					
4	Piston		Aluminum alle	oy (anodized)					
<u>(5)</u>	Disk	Aluminum alloy (special anti-abrasion treated)								
6	Spacer	Stainless steel (heat-treated)								
7	Alignment pin	Stainless steel (heat-treated)								
8	Restraining ring		Stainle	ss steel						
9	Spring		Stainle	ss steel						
10	Parallel pin	Stainless steel								
11	Steel ball	Steel								
12	Seal	Synthetic rubber (NBR)								
13	Bolt	Stainless steel								


Graph (reference values)


· Centripetal force


* Centripetal force: Force that maintains the center position via the restraining ring in a condition in which no load and no air pressure is applied.


1N = 0.225 lbf.

1mm = 0.039 in.










Retaining force · Retaining force, Retaining moment - Retaining moment

- * Retaining force: Force that maintains the center position of the X and Y directions when air pressure is applied
- * Retaining moment: Force that maintains the center position of the θ direction when air pressure is applied



Applied pressure (MPa)


0.2

0.3

0.7

0.6


CS-CPL34F CS-CPL54F



Model Code	A	В	С	D	Е	F	G	Н	J	K	L	М	N	Р	Q	R
CS-CPL34F	34 [1.339]	28 [1.102]	46 [1.811]	32 [1.260]	13 [0.512]	26 [1.024]	18 [0.709]	8.9 [0.350]	8.7 [0.343]	4 [0.157]	4.3 [0.169]	4.9 [0.193]	M3×0.5 [0.020]	3.4 [0.134]	3 [0.118]	4 [0.157]
CS-CPL54F	54 [2.126]	44 [1.732]	72 [2.835]	52 [2.047]	21 [0.827]	42 [1.654]	22 [0.866]	10.5 [0.413]	10.9 [0.429]	5 [0.197]	5.2 [0.205]	5.2 [0.205]	M5×0.8 [0.031]	5.5 [0.217]	4 [0.157]	5 [0.197]

Model Code	S	Т	U	٧	W	Х	Υ	Z	AC
CS-CPL34F	12 [0.472]	2 [0.079]	1.5 [0.059]	M3×0.5 [0.020]	6 [0.236]	4.3 [0.169]	4 [0.157]	1 [0.039]	6 [0.236]
CS-CPL54F	20 [0.787]	2.5 [0.098]	1.5 [0.059]	M5×0.8 [0.031]	7 [0.276]	5.2 [0.205]	6 [0.236]	1.5 [0.059]	9 [0.354]

CS-CPL70F CS-CPL90F



Model Code	Α	В	С	D	Е	F	G	Н	J	K	L	М	N	Р	Q	R
CS-CPL70F	70 [2.756]	58 [2.283]	92 [3.622]	70 [2.756]	30 [1.181]	60 [2.362]	25 [0.984]	11.3 [0.445]	13.1 [0.516]	6 [0.236]	6.3 [0.248]	5.5 [0.217]	M5×0.8 [0.031]	5.5 [0.217]	5 [0.197]	6 [0.236]
CS-CPL90F	90 [3.543]	74 [2.913]	116 [4.600]	90 [3.543]	40 [1.575]	80 [3.150]	28 [1.102]	12.8 [0.504]	14.5 [0.571]	6 [0.236]	7 [0.276]	5.6 [0.220]	M5×0.8 [0.031]	6.6 [0.260]	6 [0.236]	7 [0.276]

Model Code	S	Т	U	V	W	Х	Υ	Z	AA	AB	AC
CS-CPL70F	34 [1.339]	2.5 [0.098]	1.5 [0.059]	M5×0.8 [0.031]	8 [0.315]	6.3 [0.248]	7 [0.276]	1.5 [0.059]	12 [0.472]	28 [1.102]	9 [0.354]
CS-CPL90F	50 [1.969]	2.5 [0.098]	1.5 [0.059]	M6×1 [0.039]	9 [0.354]	7 [0.276]	7 [0.276]	2 [0.079]	12 [0.472]	38 [1.496]	9 [0.354]

Standard specifications Swing type



Specifications


		Basic type	CPL34S	CPL34S-N	CPL54S	CPL54S-N	CPL70S	CPL70S-N	CPL90S	CPL90S-N			
Item													
Bore size		mm [in.]	6 [0.	236]	10 [0	.394]	16 [0	0.630]	20 [0	.787]			
Dimensions		mm [in.]	□34 [□	1.339]	□54 [□	2.126]	□70 [□	□2.756]	□90 [□	□3.543]			
Height		mm [in.]	19 [0	.748]	24 [0	.945]	28 [1	.102]	32 [1	.260]			
Mass		g [oz.]	43 [1	43 [1.517] 136 [4.8] 260 [9.2] 490					490 [[17.3]			
Operating type						Single ac	ting type						
Media						А	ir						
Operating pressure	range	MPa [psi.]				0.2 to 0.7 [29.0	00 to 101.500						
Proof pressure		MPa [psi.]				1.05 [1	52.250]						
Operating temperate	ure range	°C [°F]				0 to 60 [0 t	o 140.000]						
Diameter of connec	tion port	mm [in.]	M3×0.5	5 [0.020]			M5×0.	8 [0.031]					
Lubrication	Cylinder part					Not re	quired						
Lubrication	Sliding part					N	0						
Maximum load capa	acity	kg [lb.]	1 [2.	205]	2 [4.	410]	4 [8.	.820]	6 [13	3.230]			
	X - Y	mm [in.]	±0.5 [0.020]	±1 [0	.039]	±1.5 [0.059]	±2 [0	.079]			
	Z	mm [in.]	-0.5 [-	-0.020]	-0.5 [-0.02]	-0.7 [-	-0.028]	-1.0 [-	-0.039]			
Movement range	θ (twisting)	0	±	3			±	:4					
	a (in alimation) (Swing angle	±C).5			±	:1					
	a (inclination)	Incline angle	±1	.4			±().7					
Centripetal force (when n	novement is 0.5 m	m)Note1 N [lbf.]	3 [0.674]	0 [0]	5 [1.124]	0 [0]	5 [1.124]	0 [0]	3 [0.674]	0 [0]			
Repeatability Note2 (in the direction of X and Y)	P=0.5MPa	mm [in.]				±0.05	[0.002]						
Repeatable angle accuracy $^{\text{Note3}}$ (in the direction of θ)	P=0.5MPa	Degrees		repeatability) 0.012]	±0.2 [0.008] (bidirectional repeatabil				• .				
Withstand load Note5	Pushing directi	on N [lbf.]	1580	[355]	2840 [638]		5150	50 [1158] 6670 [1499]					
with stand load	Pulling direction	n N [lbf.]	840 [188.8]	1480	[333]	2980 [670]		4880	[1097]			

- Note 1: Centripetal force: Indicates the force, with no load and no air pressure applied, that maintains the center position via the restraining ring.
- Note 2: Repeatability: The maximum deviation of the position at which the plate, with no load and no air pressure applied, stops when air has been applied after moving it in any direction. For details, see page ⑦.
- Note 3: Repeatable angle accuracy: bidirectional repeatability

The maximum deviation of the angle at which the plate, with no load and no air pressure applied, stops when air has been applied after rotating laterally. For details, see page \mathcal{D} .


- Note 4: The center position when air pressure is applied to the plate and the center position when air pressure is not applied may be misaligned.
- Note 5: When press fitting, use a load of 1/10 or less of the value for the allowable load. For details, see page ①.
- Note 6: Mount the product so that the center of gravity of the mounted load falls within the plate's external diameter, and do not operate with an overhanging load.
- Note 7: For the Handling Instructions and Precautions, see page ①.

Order Codes




Direction of movement

• X, Y, Z, θ , and α axes



Inner construction



Major parts and materials

No.	Model	CPL34S	CPL54S	CPL70S	CPL90S				
	Name	Al		too to one of the					
	Unit	Aluminu	ım alloy (elec	troless nicke	ı pıated)				
2	Frame	Aluminu	ım alloy (elec	troless nicke	l plated)				
3	Plate	Aluminu	ım alloy (elec	troless nicke	l plated)				
4	Piston		Aluminum alle	oy (anodized)				
(5)	Disk	Aluminum alloy (special anti-abrasion treated)							
6	Spacer	S	tainless steel	(heat-treate	d)				
7	Alignment pin	S	tainless steel	(heat-treate	d)				
8	Restraining ring		Stainle	ss steel					
9	Spring	Stainless steel		Piano wire					
10	Parallel pin		Stainle	ss steel					
11)	Steel ball		Steel						
12	Seal								
13	Bolt	Stainless steel							


Graph (reference values)


· Centripetal force


* Centripetal force: Force that maintains the center position via the restraining ring in a condition in which no load and no air pressure is applied.


1N = 0.225 lbf.1mm = 0.039 in.

1 MPa = 145.000 psi.










Retaining force · Retaining force, Retaining moment - Retaining moment

- * Retaining force: Force that maintains the center position of the X and Y directions when air pressure is applied
- * Retaining moment: Force that maintains the center position of the θ direction when air pressure is applied





0.10 0.05

0.00


20


0.2






CPL34S CPL54S










Model Code	Α	В	С	D	E	F	G	Ι	J	K	L	М	N	Р	Q	R
CPL34S	34 [1.339]	28 [1.102]	46 [1.811]	32 [1.260]	13 [0.512]	26 [1.024]	19 [0.748]	8.9 [0.350]	9.2 [0.399]	4 [0.157]	4.8 [0.189]	4.9 [0.193]	M3×0.5 [0.020]	3.4 [0.134]	3 [0.118]	4 [0.157]
CPL54S	54 [2.126]	44 [1.732]	72 [2.835]	52 [2.047]	21 [0.827]	42 [1.654]	24 [0.945]	10.5 [0.413]	12.4 [0.488]	5 [0.197]	6.7 [0.264]	5.2 [0.205]	M5×0.8 [0.031]	5.5 [0.217]	4 [0.157]	5 [0.197]

Model Code	S	Т	U	V	W	Х	Υ	Z
CPL34S	12 [0.472]	2 [0.079]	1.5 [0.059]	M3×0.5 [0.020]	6 [0.236]	4.8 [0.189]	4 [0.157]	1 [0.039]
CPL54S	20 [0.787]	2.5 [0.098]	1.5 [0.059]	M5×0.8 [0.031]	7 [0.276]	6.7 [0.264]	6 [0.236]	1.5 [0.059]

CPL70S CPL90S







Model Code	Α	В	С	D	Е	F	G	Н	J	K	L	М	N	Р	Q	R
CPL70S	70 [2.756]	58 [2.283]	92 [3.622]	70 [2.756]	30 [1.181]	60 [2.362]	28 [1.110]	11.3 [0.445]	14.6 [0.575]	6 [0.236]	7.8 [0.307]	5.5 [0.217]	M5×0.8 [0.031]	5.5 [0.217]	5 [0.197]	6 [0.236]
CPL90S	90 [3.543]	74 [2.913]	116 [4.600]	90 [3.543]	40 [1.575]	80 [3.150]	32 [1.260]	12.8 [0.504]	17 [0.669]	6 [0.236]	9.5 [0.374]	5.6 [0.220]	M5×0.8 [0.031]	6.6 [0.260]	6 [0.236]	7 [0.276]

Model Code	S	Т	U	V	W	Х	Υ	Z	AA	AB
CPL70S	34 [1.339]	2.5 [0.098]	1.5 [0.059]	M5×0.8 [0.031]	8 [0.315]	7.8 [0.307]	7 [0.276]	1.5 [0.059]	12 [0.472]	28 [1.102]
CPL90S	50 [1.969]	2.5 [0.098]	1.5 [0.059]	M6×1 [0.039]	9 [0.354]	9.5 [0.374]	7 [0.276]	2 [0.079]	12 [0.472]	38 [1.496]

Specifications of the improved retaining force Swing type



Specifications

		Basic type	CPLH34S	CPLH34S-N	CPLH54S	CPLH54S-N	CPLH70S	CPLH70S-N	CPLH90S-N	
Item				0. 2.10 10 11					CPLH90S	0000
Bore size		mm [in.]	16 [0	0.630]	25 [0).984]	40 [1	.575]	50 [1	1.969]
Dimensions		mm [in.]	□34 [□	□1.339]	□54 [□	□2.126]	□70 [□	□2.756]	□90 [□	□3.543]
Height		mm [in.]	26 [1	.024]	33 [1	.299]	39 [1	.535]	45 [1	1.772]
Mass		g [oz.]	65 [2	2.29]	200	[7.05]	400 [14.11]	750 [26.46]
Operating type						Single ac	ting type			
Media						Α	ir			
Operating pressure	range	MPa [psi.]				0.2 to 0.7 [29.0	00 to 101.500]		
Proof pressure		MPa [psi.]				1.05 [1	52.250]			
Operating temperatu	ire range	°C [°F]				0 to 60 [0 t	o 140.000]			
Diameter of connect	ion port	mm [in.]	M3×0.	5 [0.020]			M5×0.	8 [0.031]		
Lubrication	Cylinder part					Not re	quired			
Lubrication	Sliding part					N	0			
Maximum load capa	city	kg [lb.]	1 [2.	.205]	2 [4	.410]	4 [8	.820]	6 [13	3.230]
	X – Y	mm [in.]	±0.5 [0.020]	±1 [C	0.039]	±1.5 [0.059]	±2 [0	0.079]
	Z	mm [in.]	-0.5 [-	-0.020]	-0.5 [-0.02]	-0.7 [·	-0.028]	-1.0 [-0.039]
Movement range	θ (twisting)	0	±	:3			±	-4		
	a (in alimation) (Swing angle	±(0.5			±	 :1		
	α (inclination) $^{\circ}$	Incline angle	±1	1.4			±().7		
Centripetal force (when m	novement is 0.5 m	m)Note1 N [lbf.]	3 [0.674]	0 [0]	5 [1.124]	0 [0]	5 [1.124]	0 [0]	3 [0.674]	0 [0]
Repeatability Note2 (in the direction of X and Y)	P=0.5MPa	mm [in.]				±0.05	[0.002]			
Repeatable angle accuracy $^{\text{Note3}}$ (in the direction of θ)	P=0.5MPa	Degrees		0.008] repeatability)		±0.1	[0.004] (bidire	ctional repeatal	bility)	
Withstand load Note5	Pushing direction	on N [lbf.]	1580	[355]	2840	[638]	5150	[1158]	6670	[1499]
with istanti load notes	Pulling direction	n N [lbf.]	840 [188.8]	1480	[333]	2980	[670]	4880	[1097]

Note 1: Centripetal force: Indicates the force, with no load and no air pressure applied, that maintains the center position via the restraining ring.

Note 2: Repeatability: The maximum deviation of the position at which the plate, with no load and no air pressure applied, stops when air has been applied after moving it in any direction. For details, see page ①.


Note 3: Repeatable angle accuracy: bidirectional repeatability

The maximum deviation of the angle at which the plate, with no load and no air pressure applied, stops when air has been applied after rotating laterally. For details, see page \mathcal{D} .

- Note 4: The center position when air pressure is applied to the plate and the center position when air pressure is not applied may be misaligned.
- Note 5: When press fitting, use a load of 1/10 or less of the value for the allowable load. For details, see page ①
- Note 6: Mount the product so that the center of gravity of the mounted load falls within the plate's external diameter, and do not operate with an overhanging load.
- Note 7: For the Handling Instructions and Precautions, see page 7.


Order Codes

· Specifications of the improved retaining force, swing type




Direction of movement

• X, Y, Z, θ , and α axes





Inner construction



Major parts and materials

No.	Model	CPLH34S	CPLH54S	CPLH70S	CPLH90S						
110.	Name	0. 2	0. 2	0							
1	Unit	Aluminu	ım alloy (elec	troless nicke	l plated)						
2	Unit connection	Aluminu	ım alloy (elec	troless nicke	l plated)						
3	Frame	Aluminu	ım alloy (elec	troless nicke	l plated)						
4	Plate	Aluminu	ım alloy (elec	troless nicke	l plated)						
(5)	Piston	,	Aluminum alle	oy (anodized))						
6	Lock piston	Ste	eel (electroles	ss nickel plate	ed)						
7	Disk	Aluminum alloy (special anti-abrasion treated)									
8	Spacer	Stainless steel (heat-treated)									
9	Alignment pin	S	tainless steel	l (heat-treated	d)						
10	Restraining ring		Stainle	ss steel							
11)	Spring		Piano	wire							
12	Spring		Piano	wire							
13	Parallel pin	Stainless steel									
14)	Steel ball		Ste	eel							
15	Seal		Synthetic ru	ıbber (NBR)							
16	Bolt	Bolt Stainless steel									


Graph (reference values)


· Centripetal force


* Centripetal force: Force that maintains the center position via the restraining ring in a condition in which no load and no air pressure is applied.


1N = 0.225 lbf. 1mm = 0.039 in.

1 MPa = 145.000 psi.










• Retaining force, Retaining moment


Retaining force
Retaining moment

- * Retaining force: Force that maintains the center position of the X and Y directions when air pressure is applied
- * Retaining moment: Force that maintains the center position of the θ direction when air pressure is applied



印加圧力(MPa)


CPLH34S CPLH54S



Model Code	Α	В	С	D	E	F	G	Н	J	K	L	М	N	Р	Q	R
CPLH34S	34 [1.339]	28 [1.102]	46 [1.811]	32 [1.260]	13 [0.512]	26 [1.024]	26 [1.024]	15.9 [0.626]	9.2 [0.399]	4 [0.157]	4.8 [0.189]	4.8 [0.189]	M3×0.5 [0.020]	3.4 [0.134]	3 [0.118]	4 [0.157]
CPLH54S	54 [2.126]	44 [1.732]	72 [2.835]	52 [2.047]	21 [0.827]	42 [1.654]	33 [1.299]	19.5 [0.768]	12.4 [0.488]	5 [0.197]	6.7 [0.264]	5 [0.197]	M5×0.8 [0.031]	5.5 [0.217]	4 [0.157]	5 [0.197]

Model Code	S	T	U	V	W	Χ	Υ	Z
CPLH34S	12 [0.472]	2 [0.079]	1.5 [0.059]	M3×0.5 [0.020]	6 [0.236]	4.8 [0.189]	4 [0.157]	1 [0.039]
CPLH54S	20 [0.787]	2.5 [0.098]	1.5 [0.059]	M5×0.8 [0.031]	10 [0.394]	6.7 [0.264]	6 [0.236]	1.5 [0.059]

CPLH70S CPLH90S



Model Code	Α	В	С	D	Е	F	G	Н	J	K	L	М	N	Р	Q	R
CPLH70S	70 [2.756]	58 [2.283]	92 [3.622]	70 [2.756]	30 [1.181]	60 [2.362]	39 [1.535]	22.3 [0.878]	14.6 [0.575]	6 [0.236]	7.8 [0.307]	5 [0.197]	M5×0.8 [0.031]	5.5 [0.217]	5 [0.197]	6 [0.236]
CPLH90S	90 [3.543]	74 [2.913]	116 [4.600]	90 [3.543]	40 [1.575]	80 [3.150]	45 [1.772]	25.8 [1.016]	17 [0.669]	6 [0.236]	9.5 [0.374]	5.5 [0.217]	M5×0.8 [0.031]	6.6 [0.260]	6 [0.236]	7 [0.276]

Model Code	S	Т	U	V	W	Х	Υ	Z	AA	AB
CPLH70S	34 [1.339]	2.5 [0.098]	1.5 [0.059]	M5×0.8 [0.031]	11 [0.433]	7.8 [0.307]	7 [0.276]	1.5 [0.059]	12 [0.472]	28 [1.102]
CPLH90S	50 [1.969]	2.5 [0.098]	1.5 [0.059]	M6×1 [0.039]	14 [0.551]	9.5 [0.374]	7 [0.276]	2 [0.079]	12 [0.472]	38 [1.496]

Clean system specifications Swing type



Specifications

		Basic type	CS-CPL34S	CS-CPL34S-N	CS-CPL54S	CS-CPL54S-N	CS-CPL70S	CS-CPL70S-N	CS-CPL90S	CS-CPL90S-N		
Item			00 01 2010	00 01 20 10 K	00 01 2010	00 01 20 10 IV	00 01 2100	00 01 27 00 K	00 01 2000	00 01 2000 H		
Bore size		mm [in.]	6 [0	.236]	10 [0).394]	16 [0).630]	20 [0	.787]		
Dimensions		mm [in.]	□34 [□	□1.339]	□54 [2.126]	□70 [□	□2.756]	□90 [□	3.543]		
Height		mm [in.]	19 [0).748]	24 [0).945]	28 [1	.102]	32 [1	.260]		
Mass		g [oz.]	43 [1	.517]	136	[4.8]	260	[9.2]	490	[17.3]		
Operating type						Single ac	ting type					
Media						Α	ir					
Operating pressure	range	MPa [psi.]				0.2 to 0.7 [29.0	00 to 101.500]		_		
Proof pressure		MPa [psi.]				1.05 [1	52.250]					
Operating temperatu	ure range	°C [°F]				0 to 60 [0 t	o 140.000]					
Diameter of connect	tion port	mm [in.]	M3×0.	5 [0.020]			M5×0.	8 [0.031]				
Ileuia atia a	Cylinder part					N	0					
Lubrication	Sliding part					N	0					
Maximum load capa	city	kg [lb.]	1 [2.	.205]	2 [4	.410]	4 [8	.820]	6 [13	3.230]		
	X - Y	mm [in.]	±0.5 [0.020]	±1 [0	0.039]	±1.5 [0.059]	±2 [0	.079]		
	Z	mm [in.]	-0.5 [-	-0.020]	-0.5 [-0.02]	-0.7 [·	-0.028]	-1.0 [-0.039]		
Movement range	θ (twisting)	0	±	:3			±	-4				
	("!"\"\"-	Swing angle	±(0.5			±	:1				
	α (inclination) °	Incline angle	±1	1.4			±().7				
Centripetal force (when m	novement is 0.5 m	m)Note1 N [lbf.]	3 [0.674]	0 [0]	5 [1.124]	0 [0]	5 [1.124]	0 [0]	3 [0.674]	0 [0]		
Repeatability Note2 (in the direction of X and Y)	P=0.5MPa	mm [in.]				±0.05	0.002]					
Repeatable angle accuracy $^{\text{Note3}}$ (in the direction of θ)	P=0.5MPa	Degrees		0.012] repeatability)		±0.2	[0.008] (bidire	ctional repeatal	bility)			
Withstand load Note5	Pushing direction	on N [lbf.]	1580	[355]	2840	[638]	5150	[1158]	6670	[1499]		
withstand load notes	Pulling direction	n N [lbf.]	840 [188.8]	1480	[333]	2980	[670]	4880	[1097]		
Dust collection port		mm [in.]	M3×0.	5 [0.020]			M5×0.	8 [0.031]				
Cleanliness			Class	5 equivalent (V	hen vacuum	sucked via the	dust collection	port. Based on	Koganei stan	dards.)		

- Note 1: Centripetal force: Indicates the force, with no load and no air pressure applied, that maintains the center position via the restraining ring.

 Note 2: Repeatability: The maximum deviation of the position at which the plate, with no load and no air pressure applied, stops when air has been applied after moving it in any direction. For details, see page 7.


Note 3: Repeatable angle accuracy: bidirectional repeatability

The maximum deviation of the angle at which the plate, with no load and no air pressure applied, stops when air has been applied after rotating laterally. For details, see page 7.

- Note 4: The center position when air pressure is applied to the plate and the center position when air pressure is not applied may be misaligned.
- Note 5: When press fitting, use a load of 1/10 or less of the value for the allowable load. For details, see page ⑦.
- Note 6: Mount the product so that the center of gravity of the mounted load falls within the plate's external diameter, and do not operate with an overhanging load.
- Note 7: For the Handling Instructions and Precautions, see page 7.


Order Codes

· Clean system specifications, swing type




Direction of movement

• X, Y, Z, θ , and α axes



Inner construction



Major parts and materials

No.	Model Name	CS-CPL34S	CS-CPL54S	CS-CPL70S	CS-CPL90S					
1	Unit	Aluminu	ım alloy (elec	troless nicke	l plated)					
2	Frame	Aluminu	ım alloy (elec	troless nicke	l plated)					
3	Plate	Aluminu	ım alloy (elec	troless nicke	l plated)					
4	Piston		Aluminum alle	oy (anodized)					
<u></u>	Disk	Aluminum	alloy (specia	ıl anti-abrasio	on treated)					
6	Spacer	Stainless steel (heat-treated)								
7	Alignment pin	Stainless steel (heat-treated)								
8	Restraining ring		Stainle	ss steel						
9	Spring	Stainless steel		Piano wire						
10	Parallel pin		Stainle	ss steel						
11	Steel ball	Steel								
12	Seal	Synthetic rubber (NBR)								
13	Bolt	Stainless steel								


Graph (reference values)


· Centripetal force


* Centripetal force: Force that maintains the center position via the restraining ring in a condition in which no load and no air pressure is applied.


1N = 0.225 lbf.1mm = 0.039 in.

1 MPa = 145.000 psi.










Retaining force · Retaining force, Retaining moment - Retaining moment

- * Retaining force: Force that maintains the center position of the X and Y directions when air pressure is applied
- * Retaining moment: Force that maintains the center position of the θ direction when air pressure is applied



Applied pressure (MPa)

20


0.2

0.4

0.0




CS-CPL34S CS-CPL54S



Model Code	Α	В	С	D	Е	F	G	Н	J	K	L	М	N	Р	Q	R
CS-CPL34S	34 [1.339]	28 [1.102]	46 [1.811]	32 [1.260]	13 [0.512]	26 [1.024]	19 [0.748]	8.9 [0.350]	9.2 [0.399]	4 [0.157]	4.8 [0.189]	4.9 [0.193]	M3×0.5 [0.020]	3.4 [0.134]	3 [0.118]	4 [0.157]
CS-CPL54S	54 [2.126]	44 [1.732]	72 [2.835]	52 [2.047]	21 [0.827]	42 [1.654]	24 [0.945]	10.5 [0.413]	12.4 [0.488]	5 [0.197]	6.7 [0.264]	5.2 [0.205]	M5×0.8 [0.031]	5.5 [0.217]	4 [0.157]	5 [0.197]

Model Code	S	Т	U	V	W	Х	Υ	Z	AC
CS-CPL34S	12 [0.472]	2 [0.079]	1.5 [0.059]	M3×0.5 [0.020]	6 [0.236]	4.8 [0.189]	4 [0.157]	1 [0.039]	6 [0.236]
CS-CPL54S	20 [0.787]	2.5 [0.098]	1.5 [0.059]	M5×0.8 [0.031]	7 [0.276]	6.7 [0.264]	6 [0.236]	1.5 [0.059]	9 [0.354]


CS-CPL70S CS-CPL90S



Model Code	Α	В	С	D	E	F	G	Н	J	K	L	М	N	Р	Q	R
CS-CPL70S	70 [2.756]	58 [2.283]	92 [3.622]	70 [2.756]	30 [1.181]	60 [2.362]	28 [1.110]	11.3 [0.445]	14.6 [0.575]	6 [0.236]	7.8 [0.307]	5.5 [0.217]	M5×0.8 [0.031]	5.5 [0.217]	5 [0.197]	6 [0.236]
CS-CPL90S	90 [3.543]	74 [2.913]	116 [4.600]	90 [3.543]	40 [1.575]	80 [3.150]	32 [1.260]	12.8 [0.504]	17 [0.669]	6 [0.236]	9.5 [0.374	5.6 [0.220]	M5×0.8 [0.031]	6.6 [0.260]	6 [0.236]	7 [0.276]


Model Code	S	Т	U	V	W	Х	Υ	Z	AA	AB	AC
CS-CPL70S	34 [1.339]	2.5 [0.098]	1.5 [0.059]	M5×0.8 [0.031]	8 [0.315]	7.8 [0.307]	7 [0.276]	1.5 [0.059]	12 [0.472]	28 [1.102]	9 [0.354]
CS-CPL90S	50 [1.969]	2.5 [0.098]	1.5 [0.059]	M6×1 [0.039]	9 [0.354]	9.5 [0.374]	7 [0.276]	2 [0.079]	12 [0.472]	38 [1.496]	9 [0.354]

MEMO





MEMO





Limited Warranty

KOGANEI CORP. warrants its products to be free from defects in material and workmanship subject to the following provisions.

Warranty Period The warranty period is 180 days from the date of delivery.

Koganei Responsibility

If a defect in material or workmanship is found during the warranty period, KOGANEI CORP. will replace any part proved defective under normal use free of charge and will provide the service necessary to replace such a part.

Limitations

 This warranty is in lieu of all other warranties, expressed or implied, and is limited to the original cost of the product and shall not include any transportation fee, the cost of installation or any liability for direct, indirect or consequential damage or delay resulting from the defects.

- KOGANEI CORP. shall in no way be liable or responsible for injuries or damage to persons or property arising out of the use or operation of the manufacturer's product.
- This warranty shall be void if the engineered safety devices are removed, made inoperative or not periodically checked for proper functioning.
- Any operation beyond the rated capacity, any improper use or application, or any improper installation of the product, or any substitution upon it with parts not furnished or approved by KOGANEI CORP., shall void this warranty.
- This warranty covers only such items supplied by KOGANEI CORP. The products of other manufacturers are covered only by such warranties made by those original manufacturers, even though such items may have been included as the components.

The specifications are subject to change without notice.

URL http://www.koganei.co.jp

E-mail: overseas@koganei.co.jp



KOGANEI CORPORATION

OVERSEAS DEPARTMENT

3-11-28, Midori-cho, Koganei City, Tokyo 184-8533, Japan Tel: 81-42-383-7271 Fax: 81-42-383-7276

KOGANEI International America, Inc.

48860 Milmont Drive, Suite 108C Fremont, CA 94538, U.S.A TEL:(+1)510-744-1626 FAX:(+1)510-744-1676

SHANGHAI KOGANEI INTERNATIONAL TRADING CORPORATION

RM2606-2607, Tongda Venture Building NO.1 Lane 600, Tianshan Road, Shanghai, China TEL:(+86)021-6145-7313 FAX:(+86)021-6145-7323

TAIWAN KOGANEI TRADING CO.,LTD

Rm.2,16F.,No88,Sec.2,zhongxiao E.Rd.,ZhongZheng Dist.,Taipei City10050,Taiwan(ROC) TEL:(+886)02-2393-2717 FAX:(+886)02-2393-2719

KOGANEI KOREA CO., LTD

A-3001, Heungdeok IT Valley Bldg., Heungkeok 1-ro, 13, Giheung-gu, Yongin-si, Gyeonggi-do, 446-908, KOREA TEL:(+82)31-246-0414 FAX:(+82)31-246-0415

KOGANEI (THAILAND) CO.,LTD

555 Rasa Tower I, Unit1207, 1202, 12th floor, Phaholyothin Road, Chatuchak, Chatuchak, Bangkok 10900 Thailand TEL:(+66)02-513-1228 FAX:(+66)02-513-1232

KOGANEI ASIA PTE. LTD.

69 Ubi Road 1, #05-18 Oxley Bizhub Singapore 408731 TEL:(+65)6293-4512 FAX:(+65)6293-4513