

Office for Nuclear Regulation (ONR) Quarterly Site Report for Berkeley nuclear licensed site

Report for period 1 October - 31 December 2016

Foreword

This report is issued as part of ONR's commitment to make information about inspection and regulatory activities relating to the above site available to the public. Reports are distributed quarterly to members for the Berkeley Site Stakeholder Group and are also available on the ONR website (http://www.onr.org.uk/llc/).

A site inspector from ONR usually attends Berkeley Site Stakeholder Group meetings and will respond to any questions raised there. Any person wishing to inquire about matters covered by this report should contact ONR.

TABLE OF CONTENTS

1	INSPECTIONS	. 3
	ROUTINE MATTERS	
	NON-ROUTINE MATTERS	
	REGULATORY ACTIVITY	
	NEWS FROM ONR	
_	NTACTS	

1 INSPECTIONS

1.1 Dates of inspection

The ONR site inspector made inspections on the following dates during the quarter:

24 - 27 October 2016 inspections

The telephone conferences were also held periodically between Berkeley, the Environment Agency and ONR inspectors to discuss waste management hazard reduction activities on the site.

2 ROUTINE MATTERS

2.1 Inspections

Inspections are undertaken as part of the process for monitoring compliance with:

- The conditions attached by ONR to the nuclear site licence granted under the Nuclear Installations Act 1965 (NIA65) (as amended);
- The Energy Act 2013;
- The Health and Safety at Work Act 1974 (HSWA74); and
- Regulations made under HSWA74, for example the Ionising Radiations Regulations 1999 (IRR99) and the Management of Health and Safety at Work Regulations 1999 (MHSWR99).

The inspections entail monitoring licensee's actions on the site in relation to incidents, operations, maintenance, projects, modifications, safety case changes and any other matters that may affect safety. The licensee is required to make and implement adequate arrangements under the conditions attached to the licence in order to ensure legal compliance. Inspections seek to judge both the adequacy of these arrangements and their implementation.

In this period, routine inspections of Berkeley covered the following:

- Compliance inspections in relation to:
 - Accumulation of radioactive waste (a joint inspection with the Environment Agency Regulator)
 - Leakage and escape of radioactive material and radioactive waste (a joint inspection with the Environment Agency Regulator)
 - Decommissioning (a joint inspection with the Environment Agency Regulator)
 - Organisational capability

In general, ONR judged the arrangements made and implemented by the site in response to safety requirements to be adequate in the areas inspected. However, where improvements were considered necessary, the licensee made satisfactory commitments to address the issues, and the site inspector will monitor progress during future visits. Where necessary, ONR will take formal regulatory enforcement action to ensure that appropriate remedial measures are implemented to reasonably practicable timescales.

2.2 Other work

Nothing to report.

3 NON-ROUTINE MATTERS

Licensees are required to have arrangements to respond to non-routine matters and events. ONR inspectors judge the adequacy of the licensee's response, including actions taken to implement any necessary improvements. An ONR assessor discussed with the site the latest assessment of the future hazards and risks from the work with ionising radiation on the Berkeley site. The results of his assessment will be made know to the site in the New Year.

4 REGULATORY ACTIVITY

ONR may issue formal documents to ensure compliance with regulatory requirements. Under nuclear site licence conditions, ONR issues regulatory documents, which either permit an activity or require some form of action to be taken; these are usually collectively termed 'Licence Instruments' (LIs), but can take other forms. In addition, inspectors may issue Enforcement Notices to secure improvements to safety.

During the period no LIs were issued.

5 NEWS FROM ONR

Regulation Matters magazine

On 1 November 2016, ONR held its Industry Conference in London, which brought together senior leaders from across the nuclear sector. We were pleased to welcome Baroness Neville-Rolfe DBE CMG, Minister of State at the Department for Business, Energy and Industrial Strategy (BEIS) to this year's conference who delivered the keynote speech. A special edition of Regulation Matters has been published following the conference, which provides a summary of how the day unfolded. As part of our commitment to engage regularly with all our stakeholder groups, we were pleased to welcome 17 representatives from a number of organisations to our ONR / NGO forum on 30 November in London. The event provided an opportunity for NGO representatives to meet with a number of senior ONR leaders, including our Chief Executive and Chief Nuclear Inspector, to discuss a number of priority issues.

Insight into ONR's work as an independent regulator of the nuclear industry can be found in ONR's Regulation Matters. The online publication (http://www.onr.org.uk/regulation-matters.htm) reports on the key themes and developments in each of ONR's regulatory programmes and provides an update about the ongoing changes at ONR. http://www.onr.org.uk/index.htm. For the latest news and updates from ONR visit the website and sign up for our ebulletin (http://www.onr.org.uk/ebulletin/index.htm).

CONTACTS

Office for Nuclear Regulation Redgrave Court Merton Road Bootle Merseyside L20 7HS

website: <u>www.onr.org.uk</u>

email: ONREnquiries@onr.gsi.gov.uk

This document is issued by the Office for Nuclear Regulation (ONR). For further information about ONR, or to report inconsistencies or inaccuracies in this publication please visit http://www.onr.org.uk/feedback.htm.

© Office for Nuclear Regulation, 2017
If you wish to reuse this information visit www.onr.org.uk/copyright.htm for details. Published 1/17

For published documents, the electronic copy on the ONR website remains the most current publicly available version and copying or printing renders this document uncontrolled.