

PERFORMANCE DRAIN CLEANER

PDC is a liquid drain cleaner which rapidly clears blocked sinks, drains, and wastes. **PDC** will dissolve fats, greases, paper and natural fibrous materials. **PDC** contains inhibitors to minimize attack on metal.

PRECAUTIONS IN USE

Do not use aluminium or zinc utensils.
Do not allow diluted **PDC** to come into contact with stainless steel.
Do not use a plunger or with the plug in place.
Always add **PDC** to water. Do not add water to **PDC**.
Beware of blowbacks.

METHOD OF USE

SINKS:

1. If sink is completely blocked, bale out, leaving approx. 0.5 litres of cold water, to this add between 0.5 to 1 litre of **PDC** slowly. Leave about 10 mins. Flush with plenty of cold water.
2. If sink is not completely blocked, first pour 0.5 litres of cold water down waste pipe, followed by 0.5 to 1 litre of **PDC** slowly. Carry on as above.

DRAINS:

1. If drain is completely blocked, bale out water as much as possible, judging how much water is left. Add up to twice the amount of **PDC** slowly. Leave for about 10 mins. Flush through with plenty of cold water.
2. If drain is not completely blocked, pour in approx. 0.5 to 1 litre of cold water, and then add slowly 1 to 2 litres of **PDC**. Carry on as above.

SAFETY PRECAUTIONS

PDC is a strong acid containing 96/98% sulphuric acid.
Wear protective clothing, rubber gloves and eye protection.
In cases of contact with skin wash off with copious amounts of water.
Eyes should be irrigated with water for at least 10 mins. Seek medical attention.
For detailed health and safety information request a hazard data sheet.

PACKAGING: Boxes of 6 X 2.5 Litre

Please note that, for to safety reasons there may be restrictions on transport and delivery may require a pallet.

Paco systems
Broadridge Close
Newton Abbot
Devon TQ12 1YE

Tel: 01626 207064
Fax: 08712 424345
www.paco-systems.co.uk
info@paco-systems.co.uk

*Paints and Coatings
for Industry*