

**Reliability Laboratory** 

## TEST REPORT

Report No.: HC10206/2018 Page: 1 of 4 Date: February 8, 2018

TALITOR (FAR EAST) CO., LTD. 6F.-6, NO.646, SEC.5, CHONGSIN RD., SANCHONG DIST., NEW TAIPEI CITY, TAIWAN.

The following merchandise was submitted and identified by the vendor as:

Product Description: Style / Item No.: Manufacturer/ Vendor: Country of Origin: **Testing Period**:

2CH DVR DOS-V/ CM0713 / No.1 Talitor (Far East) Co., Ltd. Taiwan Feb. 1, 2018

We have tested the submitted sample(s) as requested and the following results were obtained: (According to client's test specification, please see following sheets in detail.) Test Required: 1. High Temperature Test

- PLEASE SEE ATTACHED SHEETS -Test Results:

#### Signed for and on behalf of SGS TAIWAN Ltd.

Hank Chiou Supervisor

No.31, No.33, No.35, Wu Chyuan Road, New Taipei Industrial Park, Wuku District, New Taipei City, Taiwan/新北市五股區新北產業園區五權路 31 號, 33 號, 35 號

Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 90 days only. This test report cannot be reproduced, except in full, without prior written permission of the Company. 除非另有說明,此報告結果僅對測試之樣品負責,同時此樣品僅保留 90 天。本報告未經本公司書面許可,不可部份複製。 This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <u>www.sqs.com/terms and conditions.htm</u> and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at <u>www.sqs.com/terms - edocument.htm</u>. Attention of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction unawful and offenders may be prosecuted to the fullest extent of the law.

SGS Taiwan Ltd. 台灣檢驗科技股份有限公司

No.134, Wu Kung Road, New Taipei Industrial Park, Wuku District, New Taipei City, Taiwan/新北市五股區新北產業園區五工路 134 號 t (886-2) 2299-3279 f (886-2) 2299-9558

www.tw.sas.com Member of SGS Group



**TEST REPORT** 

Report No.:	HC10206/2018		
Page:	2	of	4

#### **Reliability Laboratory**

## 1. High Temperature Test:

#### Test Equipment:

Name	Brand	Model	Serial No.
Programmable Temperature & Humidity Chamber	KSON	THS-D6S-150	4085

## Lab Environmental Conditions:

Ambient temperature:	<u>(25 ± 3)°C</u>
Ambient humidity:	<u>(55 ± 20)% RH</u>

## Test Method/ Specification:

Step	Temperature (°C)	Time (hour)
1	25→46	0.5
2	46	8
3	46→50	1
4	50	16
5	50→25	-

- Sample condition: Operating
- Examine the appearance of specimen(s) by visual check after test .

t (886-2) 2299-3279

Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 90 days only. This test report cannot be reproduced, except in full, without prior written permission of the Company. 除非另有說明,此報告結果僅對測試之樣品負責,可時此樣品僅保留 90 天。本報告未經本公司書面許可,不可部份複製。 This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <u>www.sqs.com/terms and conditions.htm</u> and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at <u>www.sqs.com/terms - edocument.htm</u>. Attention of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

No.31, No.35, No.35, Wu Chyuan Road, New Taipei Industrial Park, Wuku District, New Taipei City, Taiwan/新北市五股區新北產業園區五摧路 31 號, 33 號, 35 號 No.134, Wu Kung Road, New Taipei Industrial Park, Wuku District, New Taipei City, Taiwan/新北市五股區新北產業園區五工路 134 號

SGS Taiwan Ltd. 台灣檢驗科技股份有限公司\_

f (886-2) 2299-9558

www.tw.sgs.com Member of SGS Group



# TEST REPORT

Report No.:	HC10206/2018		
Page:	3	of	4

**Reliability Laboratory** 

DOS-V/ CM07	13/	No.1
Total 1 piece		

## Test Result:

Specimen:

Quantity:

Style / Item No.:

Check Item	Appearance Check
Style / Item No.	(Visual check)
DOS-V/ CM0713/ No.1	No visible damage

Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 90 days only. This test report cannot be reproduced, except in full, without prior written permission of the Company. 除非另有說明,此報告結果僅對測試之樣品負責,可時此樣品僅保留 90 天。本報告未經本公司書面許可,不可部份複製。 This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <u>www.sqs.com/terms and conditions.htm</u> and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at <u>www.sqs.com/terms - edocument.htm</u>. Attention of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

No.31, No.33, No.35, Wu Chyuan Road, New Taipei Industrial Park, Wuku District, New Taipei City, Taiwan/新北市五股區新北產業園區五摧路 31 號, 33 號, 35 號 No.134, Wu Kung Road, New Taipei Industrial Park, Wuku District, New Taipei City, Taiwan/新北市五股區新北產業園區五工路 134 號

SGS Taiwan Ltd. 台灣檢驗科技股份有限公司\_

t (886-2) 2299-3279 f (886-2) 2299-9558


www.tw.sgs.com Member of SGS Group



TEST REPORT

Report No.:	HC10206/2018		
Page:	4	of	4

Test Photos:



— The End of Test Report —

Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 90 days only. This test report cannot be reproduced, except in full, without prior written permission of the Company. 除非另有說明,此報告結果僅對測試之樣品負責,同時此樣品僅保留 90 天。本報告未經本公司書面許可,不可部份複製。 This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <u>www.sqs.com/terms and conditions.htm</u> and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at <u>www.sqs.com/terms - edocument.htm</u>. Attention of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document document approval of the Company. Any unauthorized alteration, forgery or falsification of the alternated to the fullest extent of the law.

No.31, No.35, No.35, Wu Chyuan Road, New Taipei Industrial Park, Wuku District, New Taipei City, Taiwan/新北市五股區新北產業園區五摧路 31 號, 33 號, 35 號 No.134, Wu Kung Road, New Taipei Industrial Park, Wuku District, New Taipei City, Taiwan/新北市五股區新北產業園區五工路 134 號

SGS Taiwan Ltd. 台灣檢驗科技股份有限公司\_

t (886-2) 2299-3279 f (886-2

f (886-2) 2299-9558