





looming threat of costly interruptions to production.

## CHUCKS

## CHUCK SURFACE DAMAGE COMPROMISES WORK QUALITY

A worn, damaged chuck showing cuts scribed into the ceramic surface. Surface cuts are a major cause of back face chipping and fracture of lower thickness components.

Chips and Cuts impact accuracy and the ability to hold your component securely and uniformly. Why not banish complacency and secure peace of mind with the pre-emptive strategy and sound forward planning of a business built to last?





At Loadpoint, we like to stay one step ahead of the game, and so our product development team have been busy innovating! We pioneered the technology, and now we've made that tech better in ways we'd love to share with you.

Our sophisticated chuck table systems are manufactured using fine porous ceramic and stainless steel to deliver impeccable levels of performance and tight tolerances.

## Savvy, strategic investment will;

- Reduce wastage
- Enhance efficiency
- Drive up productivity
- Increase profits and help you to gain a competitive edge.

WHY NOT GIVE US A CALL? OUR DEDICATED TEAM ARE READY TO OFFER INSIGHT, EXPERTISE, AND CUSTOM CHUCK TABLE SOLUTIONS SYMPATHETIC TO THE NEEDS OF YOUR BUSINESS.

Refurbishment options also available subject to assessment



Chelworth Industrial Estate, Cricklade, Swindon, Wiltshire, UK, SN6 6HE Tel: +44 (0)1793 751160 www.loadpoint.co.uk

