

Case Study: 14275 School Classroom and Toilets Renovation





Location
Castle View School, Slough





## **Types of Work Involved:**

Architectural & Design / Bricklaying / Carpentry / Civil Engineering / Drainage / Painting & Decorating / Roofing / Structural Engineering

## The Task:

A project incorporating internal and external works carried out at a school for Slough Borough Council.

## The Problem:

Much of the structural work was done in the school holidays, but the fitting out of the changing room had to be done when the school was in full use in school time.

## The Solution:

The biggest part of the work was creating a structure in between 4 existing buildings within the school compound so that a roof could be installed to create a changing room. In addition to this the three toilet areas were refurbished, decorated and new floors were laid in other areas.

We programed the work so that the changing room area was structurally sound and ready for fitting out. The toilet areas were completed and ready for use in school time. All work in school time was coordinated to create minimum disruption to the school.

THE JOBS FINISHED WHEN THE CLIENTS SATISFIED, NOT US.

