

## Customer Reference Story (Soak-away)

---

→ **Situation**

Caerphilly Riding Centre, South Wales. Sara Morris (Owner & Director)

→ **Critical Issue**

Patch of ground in horses field with extremely bad drainage.

→ **Reason**

Weather conditions, area where gradient leveled and no-where for the rain water to go to.

→ **Capability (when, who, what)**

A solution was required to deal with area in Horses field. Rob Morris Environmental Ltd supplied and installed the PAS108 Tyre Bales and provided full consultation to fill the bad drainage patch to then provide better drainage so the horses could use that area of the field.

→ **We Provided**

An effective and successful solution cost effectively.

→ **Result**

Area that was worked on now provides extremely improved drainage.