

Burford Electric Service, Inc.

Home of EXTENDALIFE ® VPI

154 Cooper Road/ P.O. Box 2387/ Columbus, MS 39704 Phone: 662-328-5679 Fax: 662-329-3176

www.burfordinc.com

Vibration Analysis

Reporting and Analyzing Inspection Results

Specific Equipment Routes Field Balancing
Advanced Analysis Capabilities Laser Alignment

Operational Deflection Shape Oil Analysis

Modal Analysis Ultrasonic Testing

Portable Proximity Probe Analysis

Electric Motors

Compressors Pumps
Gearboxes Blowers

HVAC

Infrared Thermography

Reporting and Analyzing Inspection Results

Substations
Capacitor Banks
Motor Control Center
Transformers
Disconnect Switches
Motor Brush Wear
Motor and Drive Couplings
Grounding Conductor
Steam Lines and Traps
Furnace Conditions

Roof Leaks Boilers

Electrical Testing

Motor Circuit Evaluation High Voltage Testing

(AC/DC Amps) (Substation) (AC/DC Volts) High Voltage

Ground Faults Testing (Switchgear Cleaning)
Ohm and Meg Testing Ultrasonic Leak Testing

24 HOUR EMERGENCY SERVICE!

Office Phone 662-328-5679 Fax 662-329-3176

Scott Tilley Lewis Cagle

Senior Analyst
Vibration Analyst: Category III
Sales/Marketing/Manager
Level I Infrared Technician

PH: 662-574-5232 PH: 662-386-0537

scott@burfordinc.com lcagle@burfordinc.com

